




# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT



**BILL RICHARDSON**

Governor

**Joanna Prukop**

Cabinet Secretary

**Mark E. Fesmire, P.E.**

Director

**Oil Conservation Division**

*Field Inspection Program  
"Preserving the Integrity of Our Environment"*

22-Apr-05

RECEIVED

MAY 19 2005

ODD-ARTESIA

**SDX RESOURCES INC**

PO BOX 5061

MIDLAND TX 79704

## NOTICE OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

### INSPECTION DETAIL SECTION

#### FEATHERSTONE FEDERAL No.001

D-22-19S-28E

30-015-02286-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
04/20/2005	Routine/Periodic	Mike Bratcher	Yes	No	5/20/2005	iMLB0511049975
<b>Violations</b> Absent Well Identification Signs (Rule 103)						
<b>Comments on Inspection:</b> No Well Sign (Rule 103). <i>Corrected 5-2-05</i>						

#### FEATHERSTONE WELCH No.001

E-22-19S-28E

30-015-02295-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
04/20/2005	Routine/Periodic	Mike Bratcher	Yes	No	5/20/2005	iMLB0511049407
<b>Violations</b> Surface Leaks/Spills						
<b>Comments on Inspection:</b> Area at wellhead is oil saturated from ongoing leak at stuffing box. Repair and cleanup required. Violation Rule 13. <i>Corrected 5-2-05</i>						