Office	State of Ne	<del>-</del>	Form C-103
District 1	Energy, Minerals and	l Natural Resources	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVA	TION DIVISION	30-015-31365 5. Indicate Type of Lease
District III	1220 South St	. Francis Dr.	STATE FEE x
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, N	IM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			Suite of the sub Boase No.
SUNDRY NOTIC	CES AND REPORTS ON W		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA"			Davis 18
PROPOSALS.)	THOM TORY ELEMENT (FORUMO	·	
1. Type of Well:			8. Well Number
Oil Well Gas Well 🗶	Other	RECEIVED	1
2. Name of Operator			9. OGRID Number
	ducing Company	JUN 2.0 2005	017891
3. Address of Operator		god-witeow	10. Pool name or Wildcat
P.O. Box 10340, Midlan	d, TX 79702-7340		McMillan Morrow
4. Well Location			
** ** **			550 010 11 11
Unit Letter D:	660 teet from the N	North line and	660 feet from the West line
Section 18	Township 20	S Range 27E	NMPM Eddy County
	11. Elevation (Show whether	er DR, RKB, RT, GR, etc.)	
	3334		
Pit or Below-grade Tank Application (For			
Pit Location: UL Sect Twp	Rng Pit type	Depth to Groundwater	Distance from nearest fresh water well
Distance from nearest surface water	Below-grade Tank Location	ULSectTwp	Rng;
feet from theline and	feet from theline	e	
12 Charle A	uuunuuista Dav ta India	ata Natura af Natica	Romant on Other Data
	ppropriate Box to Indica		
NOTICE OF INT	ENTION TO:	SUB	SEQUENT REPORT OF:
	ENTION TO:	SUB	SEQUENT REPORT OF:
NOTICE OF INT	ENTION TO: PLUG AND ABANDON	SUBS REMEDIAL WORK	SEQUENT REPORT OF:
NOTICE OF INT	ENTION TO: PLUG AND ABANDON  CHANGE PLANS	SUBS REMEDIAL WORK	SEQUENT REPORT OF:  ALTERING CASING  LLING OPNS. PLUG AND  ARANDONMENT
NOTICE OF INT	ENTION TO: PLUG AND ABANDON  CHANGE PLANS	SUBS REMEDIAL WORK COMMENCE DRIE CASING TEST AN	SEQUENT REPORT OF:  ALTERING CASING  LLING OPNS. PLUG AND
NOTICE OF INT	ENTION TO: PLUG AND ABANDON  CHANGE PLANS	SUBS REMEDIAL WORK	SEQUENT REPORT OF:  ALTERING CASING  LLING OPNS. PLUG AND  ARANDONMENT
NOTICE OF INT	ENTION TO: PLUG AND ABANDON  CHANGE PLANS	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AN CEMENT JOB	SEQUENT REPORT OF:  C
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER:	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	SUB: REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add F	SEQUENT REPORT OF:  C
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER:  13. Describe proposed or comple of starting any proposed work	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly star	SUB: REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add pute all pertinent details, and	SEQUENT REPORT OF:  ALTERING CASING  LLING OPNS. PLUG AND ABANDONMENT  DEPTS
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER:  13. Describe proposed or comple	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly star	SUB: REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add pute all pertinent details, and	SEQUENT REPORT OF:  ALTERING CASING  LLING OPNS. PLUG AND ABANDONMENT  Derfs  I give pertinent dates, including estimated date
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER:  13. Describe proposed or comple of starting any proposed work or recompletion.	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly stark). SEE RULE 1103. For N	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add processor the completions of the completion o	SEQUENT REPORT OF:  ALTERING CASING   LLING OPNS. PLUG AND ABANDONMENT  ID  Perfs  Agive pertinent dates, including estimated date ach wellbore diagram of proposed completion
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER:  13. Describe proposed or comple of starting any proposed work	ENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  ted operations. (Clearly stark). SEE RULE 1103. For M	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add processor the completions of the completion o	SEQUENT REPORT OF:  ALTERING CASING   LLING OPNS. PLUG AND ABANDONMENT  ID  Perfs  Agive pertinent dates, including estimated date ach wellbore diagram of proposed completion
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comple of starting any proposed worl or recompletion.  05/24/05 Set 1st CIBP @ 10,326'. Pt 05/25/05 Perf Morrow 10,225'-270' 05/27/05 Frac w/ 18, 650# 20/40 Cer	ENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  ted operations. (Clearly stark). SEE RULE 1103. For No. 100 March 1100 March 11	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add processor the completions of the completion o	SEQUENT REPORT OF:  ALTERING CASING   LLING OPNS. PLUG AND ABANDONMENT  ID  Perfs  Agive pertinent dates, including estimated date ach wellbore diagram of proposed completion
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comple of starting any proposed work or recompletion.  05/24/05 Set 1st CIBP @ 10,326'. Pt 05/25/05 Perf Morrow 10,225'-270'	ENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  ted operations. (Clearly stark). SEE RULE 1103. For No. 100 March 1100 March 11	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add processor the completions of the completion o	SEQUENT REPORT OF:  ALTERING CASING   LLING OPNS. PLUG AND ABANDONMENT  ID  Perfs  Agive pertinent dates, including estimated date ach wellbore diagram of proposed completion
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comple of starting any proposed worl or recompletion.  05/24/05 Set 1st CIBP @ 10,326'. Pt 05/25/05 Perf Morrow 10,225'-270' 05/27/05 Frac w/ 18, 650# 20/40 Cer	ENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  ted operations. (Clearly stark). SEE RULE 1103. For No. 100 March 1100 March 11	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add processor the completions of the completion o	SEQUENT REPORT OF:  ALTERING CASING   LLING OPNS. PLUG AND ABANDONMENT  ID  Perfs  Agive pertinent dates, including estimated date ach wellbore diagram of proposed completion
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comple of starting any proposed work or recompletion.  05/24/05 Set 1st CIBP @ 10,326'. Pt 05/25/05 Perf Morrow 10,225'-270' 05/27/05 Frac w/ 18, 650# 20/40 Cer 06/12/05 Well returned to production	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly stark). SEE RULE 1103. For M U & set 2 <sup>nd</sup> CIBP @ 10,2853 (18 holes). amax sand.	SUB: REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add proceedings and fultiple Completions: Att	SEQUENT REPORT OF:  ALTERING CASING  LLING OPNS. PLUG AND ABANDONMENT  ID  Perfs  I give pertinent dates, including estimated date ach wellbore diagram of proposed completion  O# ok.
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comple of starting any proposed work or recompletion.  05/24/05 Set 1st CIBP @ 10,326'. Pt 05/25/05 Perf Morrow 10,225'-270' 05/27/05 Frac w/ 18, 650# 20/40 Cer 06/12/05 Well returned to production  I hereby certify that the information ab	ENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  ted operations. (Clearly stark). SEE RULE 1103. For M  U & set 2 <sup>nd</sup> CIBP @ 10,285 <sup>nd</sup> (18 holes).  amax sand.  bove is true and complete to	SUB: REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add provide the least of my knowledge the my knowledge the least of my knowledge the	SEQUENT REPORT OF:  ALTERING CASING   LLING OPNS. PLUG AND ABANDONMENT  ID  Perfs  Agive pertinent dates, including estimated date ach wellbore diagram of proposed completion
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comple of starting any proposed work or recompletion.  05/24/05 Set 1st CIBP @ 10,326'. Pt 05/25/05 Perf Morrow 10,225'-270' 05/27/05 Frac w/ 18, 650# 20/40 Cer 06/12/05 Well returned to production  I hereby certify that the information at grade tank has been/will be constructed or classical constructed or	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly stark). SEE RULE 1103. For M U & set 2 <sup>nd</sup> CIBP @ 10,285 <sup>st</sup> (18 holes). amax sand. h.  Dove is true and complete to osed according to NMOCD guide	SUB: REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add provide all pertinent details, and fultiple Completions: Att	SEQUENT REPORT OF:  ALTERING CASING  ALTERING CASING  ALTERING CASING  ALTERING CASING  ABANDONMENT  ABANDONMENT  Beerfs  Agive pertinent dates, including estimated date ach wellbore diagram of proposed completion  Abandon
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comple of starting any proposed work or recompletion.  05/24/05 Set 1st CIBP @ 10,326'. Pt 05/25/05 Perf Morrow 10,225'-270' 05/27/05 Frac w/ 18, 650# 20/40 Cer 06/12/05 Well returned to production  I hereby certify that the information ab	ENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Ited operations. (Clearly stark). SEE RULE 1103. For No. (18 holes).  Tamax sand.  Dove is true and complete to osed according to NMOCD guide	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add properties all pertinent details, and fultiple Completions: Att Comple	ALTERING CASING ALTERING CASIN
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comple of starting any proposed work or recompletion.  05/24/05 Set 1st CIBP @ 10,326'. Pt 05/25/05 Perf Morrow 10,225'-270' 05/27/05 Frac w/ 18, 650# 20/40 Cer 06/12/05 Well returned to production  I hereby certify that the information at grade tank has been/will be constructed or classical constructed or	ENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Ited operations. (Clearly state). SEE RULE 1103. For No. (18 holes).  Tamax sand.  Toove is true and complete to osed according to NMOCD guide  WY  TITI	SUB: REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add provide all pertinent details, and fultiple Completions: Att	ALTERING CASING ALTERING CASIN
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comple of starting any proposed work or recompletion.  05/24/05 Set 1st CIBP @ 10,326'. Pt 05/25/05 Perf Morrow 10,225'-270' 05/27/05 Frac w/ 18, 650# 20/40 Cer 06/12/05 Well returned to production.  I hereby certify that the information at grade tank has been/will be constructed or cleaning the constructed	ENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Ited operations. (Clearly state). SEE RULE 1103. For No. (18 holes).  Tamax sand.  Toove is true and complete to osed according to NMOCD guide  WY  TITI	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add proportion of the all pertinent details, and fultiple Completions: Att Test plug & csg to 5000  the best of my knowledge clines , a general permit of the cight c@pogoproducion	ALTERING CASING CASING CASING ALTERING CASING CA
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comple of starting any proposed work or recompletion.  05/24/05 Set 1st CIBP @ 10,326'. Pt 05/25/05 Perf Morrow 10,225'-270' 05/27/05 Frac w/ 18, 650# 20/40 Cer 06/12/05 Well returned to production  I hereby certify that the information at grade tank has been/will be constructed or cle SIGNATURE	ENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Ited operations. (Clearly state). SEE RULE 1103. For No. (18 holes).  Tamax sand.  Toove is true and complete to osed according to NMOCD guide  WY  TITI	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add proportion of the all pertinent details, and fultiple Completions: Att Test plug & csg to 5000  the best of my knowledge clines , a general permit of the cight c@pogoproducion	ALTERING CASING CASING CASING ALTERING CASING CA
NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comple of starting any proposed work or recompletion.  05/24/05 Set 1st CIBP @ 10,326'. Pt 05/25/05 Perf Morrow 10,225'-270' 05/27/05 Frac w/ 18, 650# 20/40 Cer 06/12/05 Well returned to production.  I hereby certify that the information at grade tank has been/will be constructed or cleaning the constructed	ENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Ited operations. (Clearly state). SEE RULE 1103. For No. (18 holes).  Tamax sand.  Toove is true and complete to osed according to NMOCD guide  WY  TITI	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: Add proportion of the all pertinent details, and fultiple Completions: Att Test plug & csg to 5000  the best of my knowledge clines , a general permit of the cight c@pogoproducion	ALTERING CASING CASING CASING ALTERING CASING CA