RECEIVED

Form 3160-5 (September 2001)

MARBOE 3a. Address

■ Notice of Intent

Subsequent Report

Final Abandonment Notice

UNITED STATES DEDARTMENT OF THE INTERIOR

JUL 2 7 7005

Reclamation

Recomplete

☐ Water Disposal

Temporarily Abandon

FORM APPROVED OMB No. 1004-0135

☐ Well Integrity

Other

#1

	DEL WILMENT OF THE IMPRIOR	QQQ-ma-	Expires January 51, 2004
	BUREAU OF LAND MANAGEMENT	COD ARTER	🖎. Lease Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS			NMLC029395A
Do not use the abandoned we	nis form for proposals to drill or t ell. Use Form 3160-3 (APD) for suc	o re-enter an h proposals.	6. If Indian, Allottee or Tribe Name
SUBMIT IN TR	PIPLICATE - Other instructions of	on reverse side	7. If Unit or CA/Agreement, Name and/or No.
Type of Well		1 No. 1	NMNM107714
X Oil Well Gas Well C	Other		8. Well Name and No.
Name of Operator			OXY CHERRY VANILLA FED COM
MARBOB ENERGY CO	RPORATION		9. API Well No.
Address	3b. Pho	ne No. (include area code)	30-015-32463
PO BOX 227, ARTE	SIA. NM 88211-0227 (5	05) 748-3303	10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R., M., or Survey Description)			CEDAR LAKE; WOLFCAMP
			11. County or Parish, State
1980 FNL 860 FEL, SEC. 19-T17S-R31E, UNIT H			EDDY CO., NM
12. CHECK AF	PROPRIATE BOX(ES) TO INDICA	TE NATURE OF NOTICE, RI	EPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION		
	☐ Acidize ☐ Deepe	n Production (Start	(Resume) Water Shut-Off

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Fragrure Treat

XI Plug Back

New Construction

Plug and Abandon

RECOMPLETED IN THE WOLFCAMP AS FOLLOWS:

Alter Casing

Casing Repair

Change Plans

Convert to Injection

7/5/05 - COULD NOT GET PACKER LOOSE @ 11150'.

7/12/05- SET CIBP + 35' CMT @ 11050'. PERF THE PENN @ 9882'-9884' (13 SHOTS).

7/13/05- ACDZ PERF W/ 1000 GAL 15% HCL ACID.

7/14/05- SET CIBP + 35' CMT @ 9850'. PERF THE WOLFCAMP @ 8304'-8465' (9 SHOTS). ACDZ W/ 1000 GAL 15% HCL ACID. SWAB/FLOW TEST.

7/18/05- PERF THE WOLFCAMP @ 7974'-8093' (20 SHOTS). ACDZ PERFS W/ 4000 GAL 15% NEFE HCL ACID. SWAB/FLOW TEST.

14. I hereby certify that the foregoing is true and correct				
Name (Printed/Typed)				
DANA J. BRIGGS		PRODUCTION ANALYST		
Signature June June June June June June June Jun	Date JI	ULY 26, 2005		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by	Title	Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.