30-015- 34 309

CONDITIONS OF APPROVAL - DRILLING

Operator's Name:

Bass Enterprises Production Company

Well Name & No.

Poker Lake Unit #235

Location:

1980' FSL, 1930' FWL, Section 30, T, 24 S., R, 30 E., Eddy County, New Mexico

Lease:

LC-069627-A

I. DRILLING OPERATIONS REQUIREMENTS:

- 1. The Bureau of Land Management (BLM) is to be notified at the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (505) 361-2822 for wells in Eddy County in sufficient time for a representative to witness:
 - A. Well spud

B. Cementing casing:

11-3/4 inch 8-5/8 inch (if needed) 5-1/2 inch

C. BOP tests

- 2. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
- 3. Submit a Sundry Notice (Form 3160-5, one original and five copies) for each casing string, describing the casing and cementing operations. Include pertinent information such as; spud date, hole size, casing (size, weight, grade and thread type), cement (type, quantity and top), water zones and problems or hazards encountered. The Sundry shall be submitted within 15 days of completion of each casing string. The reports may be combined into the same Sundry if they fall within the same 15 day time frame.
- 4. The API No. assigned to the well by NMOCD shall be included on the subsequent report of setting the first casing string.

II. CASING:

- 1. The <u>11-3/4</u> inch surface casing shall be set at <u>approximately 550 feet and cement circulated to the surface</u>. If cement does not circulate to the surface the appropriate BLM office shall be notified and a temperature survey or cement bond log shall be run to verify the top of the cement. Remedial cementing shall be completed prior to drilling out that string.
- 2. The <u>8-5/8</u> inch intermediate casing (if needed) shall be set at <u>approximately 3465 feet and cement circulated to the surface</u>. If cement does not circulate to the surface the appropriate BLM office shall be notified and a temperature survey or cement bond log shall be run to verify the top of the cement. Remedial cementing shall be completed prior to drilling out that string.
- 3. The minimum required fill of cement behind the <u>5-1/2</u> inch production casing is to be sufficient to reach at least 500 feet above the top of the uppermost productive hydrocarbon bearing interval.

III. PRESSURE CONTROL:

- 1. All BOP systems and related equipment shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2. The BOP and related equipment shall be installed and operational before drilling below the 8-5/8 inch casing shoe and shall be tested as described in Onshore Order No. 2. Any equipment failing to test satisfactorily shall be repaired or replaced.
- 2. Minimum working pressure of the blowout preventer and related equipment (BOPE) shall be **2000** psi. Surface casing may be tested with the rig pumps.
- 3. The appropriate BLM office shall be notified in sufficient time for a representative to witness the tests.
- The results of the test shall be reported to the appropriate BLM office.
- Testing fluid must be water or an appropriate clear liquid suitable for sub-freezing temperatures. Use of drilling mud for testing is not permitted since it can mask small leaks.
- Testing must be done in a safe workman-like manner. Hard line connections shall be required.

3/4