

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-02526976
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NBR State
8. Well Number 1
9. OGRID Number
10. Pool name or Wildcat North Boot Leg Ridge

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Pogo Producing Company

3. Address of Operator

P.O. Box 10340, Midland TX 79702

4. Well Location

Unit Letter : 1980 feet from the East line and 1980 feet from the South line  
Section 18 Township 22S Range 33 E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3640 DF

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Steel Depth to Groundwater 388.05 Distance from nearest fresh water well 1060 Distance from nearest surface water 1880

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other: Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER:

THE OIL CONSERVATION DIVISION MUST  
BE NOTIFIED 24 HOURS PRIOR TO THE  
BEGINNING OF PLUGGING OPERATIONS.

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work). SEE RULE 1103. For completion of this form, attach wellbore diagram of proposed completion or recompletion.

1. POOH w/ Rods & Pump.
2. POOH w/ tubing & TAC.
3. Set C.I.B.P. @ 9846', cap w/ 5 sx of cement.
4. Circulate hole w/ 9.5 # mud.
5. Spot 35 sx Plug at 8661'.
6. Cut & pull 7 5/8" casing from 5100'.
7. Spot a 175 sx Plug at 5100' - 4800'.
8. WOC, Tag at 4800'.
9. Perforate the 10 3/4" at 3950, Sq. perforation w/ 175 sx of cement.
10. WOC, Tag at 3850'.
11. Perfo. 10 3/4" casing at 812', Sq. perfo. w/ 200 sx.
12. WOC, Tag top of cement at 700'.
13. Cut off wellhead, place a 20 sx surface Plug & a Dry Hole Marker.

100' PLUG F/1250'-1150' T.O.S.

100' PLUG F/400'-300' FRESH WATER

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE H. Boatright TITLE Agent DATE 09-16-05

Type or print name Howard Boatright

For State Use Only

E-mail address:

Telephone No.

APPROVED BY: Larry W. Wink

TITLE

DATE

Conditions of Approval (if any):

OC FIELD REPRESENTATIVE II/STAFF MAY 2005 SEP 20 2005