Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
abandoned well. Use form 3160-3 (APD) for such proposals	

SUNDRY	NIVIECU61634	6. If Indian, Allottee or Tribe Name			
Do not use th abandoned we	6. If Indian, Allottee				
SUBMIT IN TRI	7. If Unit or CA/Ag 891000303X	7. If Unit or CA/Agreement. Name and/or No. 891000303X			
1. Type of Well		8. Well Name and N PLU PHANTON	o. I BANKS 20 25 31 USA 1H		
② Oil Well ☐ Gas Well ☐ Otl  2. Name of Operator		TY HOLSTER	9. API Well No.		
BOPCO LP	E-Mail: keholster@bas		9. API Well No. 30-015-40764	-00-X1	
3a. Address		<ul><li>b. Phone No. (include area code</li><li>h: 432-683-2277</li></ul>	BIG SINKS	or Exploratory	
MIDLAND, TX 79702		RECEIV	home land		
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)	Rose Van Barn V	11. County or Parisl	h, and State	
Sec 20 T25S R31E NWNW 1: 32.122642 N Lat, 103.806088	W Lon	MAR <b>2 6</b> 2			
12. CHECK APPI	ROPRIATE BOX(ES) TO IN	NIVIOCO AFT NDICATE NATURE OF	NOTICE REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION		ТҮРЕ С	F ACTION	·	
Notice of Intent   ■ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
M Notice of filterit	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	■ Well Integrity	
☐ Subsequent Report			<b>⊠</b> Other		
☐ Final Abandonment Notice	□ Change Plans	☐ Plug and Abandon	□ Temporarily Abandon	Change to Original A PD	
	☐ Convert to Injection	□ Plug Back	■ Water Disposal	10	
testing has been completed. Final Al determined that the site is ready for f BOPCO, L.P. requests to ame Please refer to diagrams A, B We would also like to utilize a drilling of the well. This is rig without a safety problem. The end. This well is to be drilled should be +/- 2,087 psi as pre BOPE is all that is needed for are attached.	pandonment Notices shall be filed of inal inspection.)  and Point 4 Pressure Control, or C for choke manifold and armored, 5", 5,000 psi WF equipment and will help quick the hose itself is rated to 5,000 to a depth of 14,316 MD (9,4 scribed in onshore order #2 seribed.)	nly after all requirements, inclu Equipment in the original I closed loop system layor I flex hose for the choke I ken nipple up time thus sa psi and has 5,000 psi flar 83' TVD) and max surface shown as 0.22 psi/ft. Thu flex hose certification and	aving money nges on each e pressure is, a 3,000 psi	d, and the operator has	
	Electronic Submission #202 For BOP nmitted to AFMSS for process	CO LP, sent to the Carlsbaing by KURT SIMMONS on	ad 03/25/2013 (13KMS5616SE)	AKLSI	
Name (Printed/Typed) CHRISTO	PHER W GIESE	Title DRILL	ING ENGINEER	<u> </u>	
Signature (Electronic S	Submission)	Date 03/22/2	2013		
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE		
Approved By EDWARD FERNAN	DE <u>Z</u>	TitlePETROLI	EUM ENGINEER	Date 03/25/2013	
onditions of approval, if any, are attache crtify that the applicant holds legal or eq hich would entitle the applicant to condu		ad .			
				<del></del>	

#### POINT 4: PRESSURE CONTROL EQUIPMENT (SEE ATTACHED DIAGRAMS A, B, or C)

After running the 13-3/8" surface casing, a 13-5/8" BOP/BOPE system with a minimum rating of 3M will be installed, used, maintained and tested as per Onshore Order 2. In addition to the high pressure test, a low pressure (250-300 psig) test will be performed.

After running the 8-5/8" intermediate casing, a 13-5/8" or 11" BOP/BOPE system with a minimum rating of 3M will be installed on the 8-5/8" intermediate casing spool (11" open hole), used, maintained and tested as per Onshore Order 2. In addition to the high pressure test, a low pressure (250-300 psig) test will be performed.


#### **H2S** contingency


H2S monitors shall be installed prior to drilling out the surface shoe. If H2S is encountered in quantities greater than 10 PPM, the well will be shut in and H2S equipment will be installed, including a flare line that will be extended pursuant to onshore oil and gas order #6.


These tests will be performed:

- a) Upon installation
- b) After any component changes
- c) Thirty days after a previous test
- d) As required by well conditions
- e) Any time a seal is broken within a system

A function test to insure that the preventers are operating correctly will be performed on each trip.









# Midwest Hose & Specialty, Inc.

INTERN	AL HYDI	ROST	TATIC TES	ST REPO	ORT	`
Customer:				Customer P.O. Number:		
LATSHAW					147340	
	HOSES	SPECI	FICATIONS			
Type: Rotary / Vibrator Hose						
C & K	/ API 7	(		Hose Lei	ngth: 3	5FT 8 IN
I.D.	3.5 INC	HES	O.D.	5.02	//	ICHES
WORKING PRESSURE	TEST P	RESSUR	E .	BURST P	RESSURE	
5,000 <i>P</i> S	,	5,000	PSI		N/A	PSI
			LINGS			
Part Number	Stem L			Ferrule	Lot Nu	mber
D3.5X64WB	Joenn L		LOT1	i .		
		IA		NA		
Type of Coupling:			Die Size:	······································		
Swage-It			5.75 INCHES			
,		PROC	EDURE			
· .					,	
Hose assembly pressure tested with water at ambient temperature.  TIME HELD AT TEST PRESSURE ACTUAL BURST PRESSURE:				•		
TIME HELD AT TEST PRESSURE			ACTUAL	. BUKSI MKE	550KE.	
9 1	1/4	MIN.			N/A	PSI
Hose Assembly Serial Number: Hose Serial Number:						
1473	40		<u> </u>	NA		
Comments:	HOSE R	EPAIR				
Date:	Tested:			Approved:	·····	· · · · · · · · · · · · · · · · · · ·
4/11/2012	10	IN	Canibra	Kim	Ahom	20

## Michwest Hose & Specialty, Inc.

### Internal Hydrostatic Test Graph

Customer: Latshaw


Pick Ticket #: 147340

#### Hose Specifications

Hose Type	Length
D	35' 8"
I.D.	<u>O.D.</u>
3.5"	5.02"
Working Pressure	Burst Pressure
SOUP DO	Fr

#### **Verification**

Type of Fitting	Coupling Method
4 1/16 5K	Swage
Die Size	Final O.D.
5.75"	5.79***
Hose Serial #	Hose Assembly Serial
NA	147340



Test Pressure 5000 PSI Time Held at Test Pressure
9 1/4 Minutes

Actual Burst Pressure

Peak Pressure 5786 PSI

Comments: Hose assembly pressure tested with water at ambient temperature.

lested By: Donnie Mciemo.

Approved By: Kim Thornos

#### CONDITIONS OF APPROVAL

BOP/BOPE Sundry dated 3/22/2013

OPERATOR'S NAME: | CHESAPEAKE OPERATING FOR BOPCO, LP

LEASE NO.: LC061634B

WELL NAME & NO.: | 1H-PLU PHANTOM BANKS 20 25 31 USA

SURFACE HOLE FOOTAGE: 150'/N. & 660'/W. BOTTOM HOLE FOOTAGE 100'/S. & 660'/W.

LOCATION: | Section 20, T. 25 S., R. 31 E., NMPM

COUNTY: | Eddy County, New Mexico

#### Original COA still applies with the following changes:

#### A. PRESSURE CONTROL

- 1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 2. Variance approved to use flex line from BOP to choke manifold. Check condition of flexible line from BOP to choke manifold, replace if exterior is damaged or if line fails test. Line to be as straight as possible with no hard bends and is to be anchored according to Manufacturer's requirements. The flexible hose can be exchanged with a hose of equal size and equal or greater pressure rating. Anchor requirements, specification sheet and hydrostatic pressure test certification matching the hose in service, to be onsite for review. If the BLM inspector questions the straightness of the hose, a BLM engineer will be contacted and will review in the field or via picture supplied by inspector to determine if changes are required (operator shall expect delays if this occurs).
- 3. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **3000** (**3M**) psi.
  - a. For surface casing only: If the BOP/BOPE is to be tested against casing, the wait on cement (WOC) time for that casing is to be met (see WOC statement at start of casing section). Independent service company required.
- 4. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
  - a. In a water basin, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. The casing cut-off and BOP installation can be initiated four hours after installing the slips, which will be approximately six hours after bumping the plug. For those casing strings not using slips, the minimum wait time before cut-off is eight hours after bumping the plug. BOP/BOPE testing can begin after cut-off or once cement reaches 500 psi compressive strength (including

lead when specified), whichever is greater. However, if the float does not hold, cut-off cannot be initiated until cement reaches 500 psi compressive strength (including lead when specified).

- b. The tests shall be done by an independent service company utilizing a test plug **not** a **cup** or **J-packer**. The operator also has the option of utilizing an independent tester to test without a plug (i.e. against the casing) pursuant to Onshore Order 2 with the pressure not to exceed 70% of the burst rating for the casing. Any test against the casing must meet the WOC time for water basin (18 hours) or potash (24 hours) or 500 pounds compressive strength, whichever is greater, prior to initiating the test (see casing segment as lead cement may be critical item).
- c. The results of the test shall be reported to the appropriate BLM office.
- d. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
- e. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug.

EGF 032213