Form 3160-5 (August 2007)	UNITED STATE		OCD Arte			I APPROVED NO. 1004-0135	
1	DEPARTMENT OF THE I BUREAU OF LAND MANA NOTICES AND REPO	AGEMENT				: July 31, 2010	
	his form for proposals to ell. Use form 3160-3 (AF					or Tribe Name	
	RIPLICATE - Other instru		Address C.			eement, Name and/or No.	
1. Type of Well					8. Well Name and No. NDDUP UNIT 7		
Oil Well □ Gas Well □ Other Contact: TINA HUERTA YATES PETROLEUM CORPORATION€-Mail: tinah@yatespetroleum.com					9. API Well No. 30-015-27165		
3a. Address 105 SOUTH FOURTH STREET ARTESIA, NM 88210		3b. Phone No. (include area code) Ph: 575-748-4168 Fx: 575-748-4585			10. Field and Pool, or Exploratory N.SEVEN RIVERS;GLOR-YESO		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish,	and State	
Sec 17 T19S R25E NENW 6			EDDY COUNT	Y, NM			
12. CHECK API	PROPRIATE BOX(ES) T	O INDICATE	NATURE OF 1	NOTICE, RE	PORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					<u> </u>	
Notice of Intent	□ Acidize	🗖 Deep		Producti	on (Start/Resume)	🗖 Water Shut-Off	
Subsequent Report	Alter Casing		are Treat	🗖 Reclama		U Well Integrity	
	Casing Repair	—	Construction	C Recomp		🗖 Other	
Final Abandonment Notice	Change Plans		and Abandon Back	U Tempora	arily Abandon isposal		
testing has been completed. Final A determined that the site is ready for RESUBMIT Yates Petroleum Corporation safety equipment as needed. top. Set a 100 sx cement plu casing to 3500 psi., Pull a CE secondary cement job to get 2190'-2568' (70). Frac treat a to 3400 psig. Set a pop off v 3-1/2 inch P-110 tubing and t sand laden fluid stages will b remain the same. Frac detai	final inspection.) n plans to plugback and re NU BOP. Run GR/JB to ug from 4959'-5520' across BL/GR/CCL to determine T TOC to 1690'; this may al at 75 BPM down 7 inch ca alve at 3600 psi. If we hav the rate will be 40 BPM will e cut by 50% to only 8050 Is attached. Flow well back is true and correct. Electronic Submission # For YATES PETRO	complete this w o 7720'. Set a C s Wolfcamp top TOC, if necessa iter the frac pun sing limiting the d to squeeze th ht a max press 0 of 16/30 all o ck and allow we	vell as follows: CIBP at 7715' w and DV tool. Iry perforate ar ap schedule. P e surface treating is job will be pour ure of 8500 psi ther stage volu and the	Rig up all vith 35' ceme Pressure test depump a Perforate Yes mg pressure umped via and the 16/3 mes will TIH with	SUBJEC SEE APPRO SEE ATTA(CONDITIO	CT TO LIKE VAL BY STATE C 102	
Committed to AFMSS for processing Name(Printed/Typed) TINA HUERTA			•	,	2013 () CUPERVISOR	parties of p	
Signature (Electronic	Submission)		Date 03/04/2	013	APPR	ROVED	
	THIS SPACE FO	OR FEDERAL	OR STATE	OFFICE U	E		
Approved By			Title		APR	1 0 2013	
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.						1 Jung	
certify that the applicant holds legal or ec	uitable title to those rights in the		Office		BUREAU OF LAI	MANAGEME NT FIELD OFFICE	

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Additional data for EC transaction #200492 that would not fit on the form

32. Additional remarks, continued

5

;

tubing to check for fill and to ensure the perforations are not covered. POOH. TIH with tubing, swab well until it cleans up then TIH with pumping equipment and turn well to production. Wellbore schematics attached. Well name will change back to Jenny Com #2 after recompletion.

Conditions of Approval

Yates Petroleum Corporation North Dagger Draw Upper Penn Unit 7 API 30-015-27165 T19S-R25E, Sec 17 April 10, 2013

- 1. Submit electronic copy of CBL to BLM for review and to concur with top of cement.
- 2. CIBP shall be set at 7715' and operator shall place 35' cement on top. Tag required.
- 3. Operator shall place a balanced cement plug across the Wolfcamp formation and DVtool as proposed.
- 4. Submit results of the MIT to the BLM. If MIT fails, submit remedial plan to BLM.
- 5. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 6. Subject to like approval by the New Mexico Oil Conservation Division.
- 7. Notify BLM 575-200-7902 Eddy County as work begins. Some procedures are to be witnessed. If no answer, leave a voice mail with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.
- 8. Surface disturbance beyond the existing pad must have prior approval.
- 9. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 10. Functional H₂S monitoring equipment shall be on location.

5

- 11. 2000 (2M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. A ram of the work string(s) used is required equipment. Manuel BOP closure system including a blind ram and pipe ram(s) designed to close on all (hand wheels) equipment shall be installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 12. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 13. The BLM PET witness is to run tbg tally and agree to cement placement. Sample each plug for cement curing time and tag and/or pressure test (WOC time of 4 hours recommended) as requested by BLM PET witness.

- 14. Class H > 7500ft & C < 7500ft) cement plugs(s) will be necessary. The minimum pumped volume of 25 sacks of cement slurry is to exceed a 100ft cement plug across the drilled wellbore. Add 10% to the 100ft slurry volume for each 1000ft of plug depth when calculations indicate the need. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 15.6#/gal, 1.18ft³/sx, 5.2gal/sx water.
- 15. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 16. File intermediate **subsequent sundry** Form 3160-**5** within 30 days of any interrupted workover procedures and a complete workover subsequent sundry. File the subsequent sundry for the frac separately if it is delayed as much as 20 days.
- 17. Submit the BLM Form 3160-4 **Recompletion Report** within 30 days of the date all BLM approved procedures are complete.
- 18. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.
- 19. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment.
- 20. Remove unit from the name.

JAM 041013

2