
			OCD Arte	esla			
Form 3160-5 (August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR				FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010			
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMNM117116	5. Lease Serial No.	
						6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well				8. Well Name and No. COTTON HILLS 23 26 27 FED COM 1H			
□ Oil Well ☑ Gas Well □ Other 2. Name of Operator CHESAPEAKE OPERATING INC Contact: KYLE R JOHNS E-Mail: kyle.johnson@chevron.com				9. API Well No. 30-015-41535-00-X1			
3a. Address	3b. Phone No. (include area code) Ph: 713-372-6514			10. Field and Pool, or Exploratory HAY HOLLOW			
OKLAHOMA CITY, OK 73154-0496 4. Location of Well (Footage, Sec., T., R., M. or Survey Description)					11. County or Parish, and State		
Sec 23 T26S R27E NWNE 152FNL 1979FEL 32.034440 N Lat, 104.158190 W Lon			EDDY COUNTY, NM			Y, NM	
12. CHECK APP	ROPRIATE BOX(ES) TO) INDICATE	ENATURE OF	NOTICE,	REPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
X Notice of Intent	A Notice of Intent		—	Production (Start/Resume) 🔲 Water Shut-Off			
Subsequent Report	Alter Casing	_	racture Treat			Well Integrity	
☐ Final Abandonment Notice			—	nplete 🛛 Other orarily Abandon PD • Disposal			
	Convert to Injection						
 13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for f Chevron respectfully requests GE/Vetco SH-2 Multi-bowl we surface casing to 5,000 psi hi exceed 21 days from the prev test information will be provide Please see the attached wellh 	ally or recomplete horizontally, rk will be performed or provide d operations. If the operation re bandonment Notices shall be fil inal inspection.) to to change plans for BOP ilhead. Chevron respectfu gh and 250 psi low, and to rious test. The field report ed in a subsequent report	give subsurface the Bond No. o sults in a multip led only after all P testing due f ully requests to perform sub from GE/Vet at the end of	locations and measu n file with BLM/BL le completion or rec requirements, inclue to the utilization of to nipple up and osequent tests as co representativi the well.	ured and true A. Required ompletion ir ding reclama of the test BOPI s needed, e and the	e vertical depths of all pertir subsequent reports shall be a new interval, a Form 316 tion, have been completed, E on the not	hent markers and zones. filed within 30 days i0-4 shall be filed once and the operator has CEIVED 0 7 2013	
	Electronic Submission #	AKE OPERATI	NG INC, sent to t NY DICKERSON	the Carlsb	ad 013 (13JLD1019SE)		
						, Without a the fi	
Signature (Electronic	Submission) THIS SPACE FO		Date 07/25/2		USE	<u></u>	
	1.		D.T		······································	aleli	
Approved By MUM Conditions of approval, if any, are attached. Approval of this notice does not certify that the applicant holds legal or equitable title to those rights in the sub			Title Telm	leurn	Engineer	Date 8/5/13	
certify that the applicant holds legal or eq							
certify that the applicant holds legal or eq which would entitle the applicant to cond Title 18 U.S.C. Section 1001 and Title 43	uct operations thereon.		Office				

Ŷ

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **





30		нар Изг 5м		·
	This drawing is the property of GE Oil & Gas Pressure Control LP and is considered confidential. Unless otherwise approved in writing, neither it nor its contents may be used, copied, transmitted or reproduced except for the sole purpose of GE Oil & Gas Pressure Control LP.			J.S.A. BASIN
13-3/8" x 9-5/8" x	DRAWN	BLZ	04DEC12	
	APPRV	VJK	04DEC12	
Wellhead Ass	FOR REFERENCE ONLY			
T-EN Tubin	DRAWING N	o. AE2	3014-A	
DOC NOT RELEA	SED.	·	na s Nin Landador	

GE Oil & Gas Drilling & Production

Pressure Control Wellhead Equipment Running Procedure For:

13-3/8" x 9-5/8" x 7" x 2-7/8" 10/3M SH2/SH2-R Wellhead Assembly

Publication # RP-1986 November, 2011



CONDITIONS OF APPROVAL

OPERATOR'S NAME:	Chevron
LEASE NO.:	NM117116
WELL NAME & NO.:	1H-COTTON HILLS 23 26 27 FED COM
SURFACE HOLE FOOTAGE:	152' FNL & 1979' FEL
BOTTOM HOLE FOOTAGE	560' FSL & 1979' FSL
LOCATION:	Section 23, T. 26 S., R 27 E., NMPM
COUNTY:	Eddy County, New Mexico

PRESSURE CONTROL

 \mathcal{T}

- 1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 2. Variance approved to use flex line from BOP to choke manifold. Check condition of flexible line from BOP to choke manifold, replace if exterior is damaged or if line fails test. Line to be as straight as possible with no hard bends and is to be anchored according to Manufacturer's requirements. The flexible hose can be exchanged with a hose of equal size and equal or greater pressure rating. Anchor requirements, specification sheet and hydrostatic pressure test certification matching the hose in service, to be onsite for review. These documents shall be posted in the company man's trailer and on the rig floor. If the BLM inspector questions the straightness of the hose, a BLM engineer will be contacted and will review in the field or via picture supplied by inspector to determine if changes are required (operator shall expect delays if this occurs).
- Operator has proposed a multi-bowl wellhead assembly. This assembly will only be tested when installed on the surface casing. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be 5000 (5M) psi.
 5M system requires an HCR valve, remote kill line and annular to match. The remote kill line is to be installed prior to testing the system and tested to stack pressure.
 - a. Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.
 - b. If the welding is performed by a third party, the manufacturer's representative shall monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
 - c. Manufacturer representative shall install the test plug for the initial BOP test.
 - d. Operator shall perform the intermediate casing integrity test to 70% of the casing burst. This will test the multi-bowl seals.

- e. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.
- 4. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
 - a. In a water basin, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. The casing cut-off and BOP installation can be initiated four hours after installing the slips, which will be approximately six hours after bumping the plug. For those casing strings not using slips, the minimum wait time before cut-off is eight hours after bumping the plug. BOP/BOPE testing can begin after cut-off or once cement reaches 500 psi compressive strength (including lead when specified), whichever is greater. However, if the float does not hold, cut-off cannot be initiated until cement reaches 500 psi compressive strength (including lead when specified).
 - b. The tests shall be done by an independent service company utilizing a test plug **not a cup or J-packer**. The operator also has the option of utilizing an independent tester to test without a plug (i.e. against the casing) pursuant to Onshore Order 2 with the pressure not to exceed 70% of the burst rating for the casing. Any test against the casing must meet the WOC time for water basin (18 hours) or potash (24 hours) or 500 pounds compressive strength, whichever is greater, prior to initiating the test (see casing segment as lead cement may be critical item).
 - c. The test shall be run on a 5000 psi chart for a 2-3M BOP/BOP, on a 10000 psi chart for a 5M BOP/BOPE and on a 15000 psi chart for a 10M BOP/BOPE. If a linear chart is used, it shall be a one hour chart. A circular chart shall have a maximum 2 hour clock.
 - d. The results of the test shall be reported to the appropriate BLM office.
 - e. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
 - f. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug. This test shall be performed prior to the test at full stack pressure.

g. BOP/BOPE must be tested by an independent service company within 500 feet of the top of the **Wolfcamp** formation if the time between the setting of the intermediate casing and reaching this depth exceeds 20 days. This test does not exclude the test prior to drilling out the casing shoe as per Onshore Order No. 2.

CRW 080513

s

7