Scienti I Copy To Appropriate District	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161 <u>Ener</u>	gy. Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NN 88 40 CEIVE	D .^	WELL API NO.
811 S. First St. Artesia NM 88210 OII	CONSERVATION DIVISION	30-015-31913 5. Indicate Type of Lease
District III – (505) 334-6178 AUG 12 2013	1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec NM 87410	Conto Eo NIM 97505	6. State Oil & Gas Lease No.
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa NMOCD ARTES 87505	SIA J	V-2705
SUNDRY NOTICES AND	REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DR		Graham AKB State
DIFFERENT RESERVOIR. USE "APPLICATION FOR	R PERMIT" (FORM C-101) FOR SUCH	8. Well Number
PROPOSALS.) 1. Type of Well: Oil Well Gas Well	Other	8
2. Name of Operator		9. OGRID Number
Yates Petroleum Corporation		025575 10. Pool name or Wildcat
3. Address of Operator 105 South Fourth Street, Artesia, NM 88210		Lost Tank, Delaware
4. Well Location		
	et from the North line and	330 feet from the West line
	ownship 22S Range 31E	NMPM Eddy County
11. Elev	ation (Show whether DR, RKB, RT, GR, etc.	2.)
3514' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTIC	ON TO:	BSEQUENT REPORT OF:
	ND ABANDON ☐ REMEDIAL WO	
	— 1	RILLING OPNS. P AND A
	LE COMPL CASING/CEMEN	
DOWNHOLE COMMINGLE	0,10,110,02,1112.	
		_
OTHER:	OTHER:	and aires mantinent dates, in alleding actionated date
13. Describe proposed or completed opera	ations. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date
13. Describe proposed or completed opera of starting any proposed work). SEE	ations. (Clearly state all pertinent details, and RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or completed opera	ations. (Clearly state all pertinent details, and RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or completed opera of starting any proposed work). SEE proposed completion or recompletion.	ations. (Clearly state all pertinent details, and RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
 13. Describe proposed or completed opera of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure testing of the proposed completion. 	Attions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 19.15.7.14 NMAC. Fo	swinging. s. Set packer at 5342'. Pressure test down
 13. Describe proposed or completed opera of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure testubing and casing from 5342' to RBP 	Attions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 1/2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good	swinging. s. Set packer at 5342'. Pressure test down Hole in the casing from 5307-5342'. Pressure
13. Describe proposed or completed opera of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure testubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 mir	Ations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. /2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good as. Tried to get an injection rate into the ho	swinging. s. Set packer at 5342'. Pressure test down
of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure testubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 mir Tagged RBP at 6379'. Tagged up on	Ations. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. /2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good is. Tried to get an injection rate into the hor RBP at 6384'.	swinging. s. Set packer at 5342'. Pressure test down Hole in the casing from 5307-5342'. Pressure ple pressured up to 3000 psi. Released packer.
13. Describe proposed or completed opera of starting any proposed work). SEE 1 proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1 6/25/13 – Set packer at 5307'. Pressure test tubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 mir Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and	Actions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 1/2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good as. Tried to get an injection rate into the hor RBP at 6384'. perf'd at 5342'. TIH with packer. Set at 5	swinging. s. Set packer at 5342'. Pressure test down Hole in the casing from 5307-5342'. Pressure ble pressured up to 3000 psi. Released packer.
13. Describe proposed or completed operation of starting any proposed work). SEE 1 proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1 6/25/13 – Set packer at 5307'. Pressure testubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 mir Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and released packer. Gauge ring down to 2	Actions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 1/2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good as. Tried to get an injection rate into the hor RBP at 6384'. perf'd at 5342'. TIH with packer. Set at 55520'. RIH with 5-1/2" retainer, set at 525	swinging. s. Set packer at 5342'. Pressure test down . Hole in the casing from 5307-5342'. Pressure ble pressured up to 3000 psi. Released packer. 5307'. Pumped 30 bbls into formation and 57'. TIH with stinger. Tagged up and sting into
of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure testubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 min Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and released packer. Gauge ring down to retainer. Could not pump thru. Tried	Actions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 1/2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good as. Tried to get an injection rate into the hor RBP at 6384'. perf'd at 5342'. TIH with packer. Set at 55520'. RIH with 5-1/2" retainer, set at 525 to jet out retainer still could not pump thru	swinging. s. Set packer at 5342'. Pressure test down Hole in the casing from 5307-5342'. Pressure ble pressured up to 3000 psi. Released packer. 307'. Pumped 30 bbls into formation and 57'. TIH with stinger. Tagged up and sting into
of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure testubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 min Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and released packer. Gauge ring down to retainer. Could not pump thru. Tried	Actions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 1/2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good as. Tried to get an injection rate into the hor RBP at 6384'. perf'd at 5342'. TIH with packer. Set at 55520'. RIH with 5-1/2" retainer, set at 525 to jet out retainer still could not pump thru	swinging. s. Set packer at 5342'. Pressure test down Hole in the casing from 5307-5342'. Pressure ole pressured up to 3000 psi. Released packer. 307'. Pumped 30 bbls into formation and 37'. TIH with stinger. Tagged up and sting into the could not keep retainer in the shoe. TOOH.
of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure testubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 min Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and released packer. Gauge ring down to retainer. Could not pump thru. Tried	Actions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 1/2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good as. Tried to get an injection rate into the hor RBP at 6384'. perf'd at 5342'. TIH with packer. Set at 55520'. RIH with 5-1/2" retainer, set at 525 to jet out retainer still could not pump thru	swinging. s. Set packer at 5342'. Pressure test down Hole in the casing from 5307-5342'. Pressure ble pressured up to 3000 psi. Released packer. 307'. Pumped 30 bbls into formation and 57'. TIH with stinger. Tagged up and sting into
of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure testubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 mir Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and released packer. Gauge ring down to retainer. Could not pump thru. Tried 6/27/13 – Tagged up on retainer at 5257'.	Actions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 1/2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good as. Tried to get an injection rate into the hor RBP at 6384'. perf'd at 5342'. TIH with packer. Set at 55520'. RIH with 5-1/2" retainer, set at 525 to jet out retainer still could not pump thru Milled over retainer. Tagged up on retainer	swinging. s. Set packer at 5342'. Pressure test down Hole in the casing from 5307-5342'. Pressure ole pressured up to 3000 psi. Released packer. 307'. Pumped 30 bbls into formation and 37'. TIH with stinger. Tagged up and sting into the could not keep retainer in the shoe. TOOH.
of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure testubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 min Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and released packer. Gauge ring down to retainer. Could not pump thru. Tried	Actions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 1/2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good as. Tried to get an injection rate into the hor RBP at 6384'. perf'd at 5342'. TIH with packer. Set at 55520'. RIH with 5-1/2" retainer, set at 525 to jet out retainer still could not pump thru	swinging. s. Set packer at 5342'. Pressure test down Hole in the casing from 5307-5342'. Pressure ole pressured up to 3000 psi. Released packer. 307'. Pumped 30 bbls into formation and 37'. TIH with stinger. Tagged up and sting into the could not keep retainer in the shoe. TOOH.
of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure testubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 mir Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and released packer. Gauge ring down to retainer. Could not pump thru. Tried 6/27/13 – Tagged up on retainer at 5257'.	Actions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 1/2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good as. Tried to get an injection rate into the hor RBP at 6384'. perf'd at 5342'. TIH with packer. Set at 55520'. RIH with 5-1/2" retainer, set at 525 to jet out retainer still could not pump thru Milled over retainer. Tagged up on retainer	swinging. s. Set packer at 5342'. Pressure test down Hole in the casing from 5307-5342'. Pressure ole pressured up to 3000 psi. Released packer. 307'. Pumped 30 bbls into formation and 37'. TIH with stinger. Tagged up and sting into the could not keep retainer in the shoe. TOOH.
of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure testubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 mir Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and released packer. Gauge ring down to retainer. Could not pump thru. Tried 6/27/13 – Tagged up on retainer at 5257'.	Attions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Control of Parker and TIH leaving packer at casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good as. Tried to get an injection rate into the hor RBP at 6384'. 1. perf'd at 5342'. TIH with packer. Set at 55520'. RIH with 5-1/2" retainer, set at 525 to jet out retainer still could not pump thrum Milled over retainer. Tagged up on retainer. 1. Rig Release Date:	swinging. s. Set packer at 5342'. Pressure test down . Hole in the casing from 5307-5342'. Pressure ole pressured up to 3000 psi. Released packer. 3307'. Pumped 30 bbls into formation and 57'. TIH with stinger. Tagged up and sting into . er. Could not keep retainer in the shoe. TOOH. CONTINUED ON NEXT PAGE:
13. Describe proposed or completed opera of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure testubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 mir Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and released packer. Gauge ring down to retainer. Could not pump thru. Tried 6/27/13 – Tagged up on retainer at 5257'. Spud Date:	Actions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 1/2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good is. Tried to get an injection rate into the hor RBP at 6384'. perf'd at 5342'. TIH with packer. Set at 55520'. RIH with 5-1/2" retainer, set at 525 to jet out retainer still could not pump thru Milled over retainer. Tagged up on retainer. Rig Release Date:	swinging. s. Set packer at 5342'. Pressure test down . Hole in the casing from 5307-5342'. Pressure ole pressured up to 3000 psi. Released packer. 3307'. Pumped 30 bbls into formation and 57'. TIH with stinger. Tagged up and sting into . er. Could not keep retainer in the shoe. TOOH. CONTINUED ON NEXT PAGE:
13. Describe proposed or completed opera of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure testubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 mir Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and released packer. Gauge ring down to retainer. Could not pump thru. Tried 6/27/13 – Tagged up on retainer at 5257'. Spud Date:	Actions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 1/2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good is. Tried to get an injection rate into the hor RBP at 6384'. perf'd at 5342'. TIH with packer. Set at 55520'. RIH with 5-1/2" retainer, set at 525 to jet out retainer still could not pump thru Milled over retainer. Tagged up on retainer. Rig Release Date:	swinging. s. Set packer at 5342'. Pressure test down . Hole in the casing from 5307-5342'. Pressure ole pressured up to 3000 psi. Released packer. 6307'. Pumped 30 bbls into formation and 67'. TIH with stinger. Tagged up and sting into 69. CONTINUED ON NEXT PAGE:
13. Describe proposed or completed opera of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure testubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 mir Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and released packer. Gauge ring down to retainer. Could not pump thru. Tried 6/27/13 – Tagged up on retainer at 5257'. Spud Date:	Actions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 1/2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good is. Tried to get an injection rate into the hor RBP at 6384'. perf'd at 5342'. TIH with packer. Set at 55520'. RIH with 5-1/2" retainer, set at 525 to jet out retainer still could not pump thru Milled over retainer. Tagged up on retainer. Rig Release Date:	swinging. s. Set packer at 5342'. Pressure test down . Hole in the casing from 5307-5342'. Pressure ole pressured up to 3000 psi. Released packer. 3307'. Pumped 30 bbls into formation and 57'. TIH with stinger. Tagged up and sting into . er. Could not keep retainer in the shoe. TOOH. CONTINUED ON NEXT PAGE:
13. Describe proposed or completed opera of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure test tubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 mir Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and released packer. Gauge ring down to retainer. Could not pump thru. Tried 6/27/13 – Tagged up on retainer at 5257'. Spud Date: I hereby certify that the information above is trivial to the pump that the single packer. Gauge ring down to retainer. Could not pump thru. Tried 6/27/13 – Tagged up on retainer at 5257'.	Actions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 1/2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good is. Tried to get an injection rate into the hor RBP at 6384'. perf'd at 5342'. TIH with packer. Set at 55520'. RIH with 5-1/2" retainer, set at 525 to jet out retainer still could not pump thru Milled over retainer. Tagged up on retainer. Rig Release Date:	swinging. s. Set packer at 5342'. Pressure test down . Hole in the casing from 5307-5342'. Pressure ole pressured up to 3000 psi. Released packer. 3307'. Pumped 30 bbls into formation and it'. TIH with stinger. Tagged up and sting into . er. Could not keep retainer in the shoe. TOOH. CONTINUED ON NEXT PAGE: Geard Date August 7, 2013
13. Describe proposed or completed opera of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure test tubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 mir Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and released packer. Gauge ring down to retainer. Could not pump thru. Tried 6/27/13 – Tagged up on retainer at 5257'. Spud Date:	Actions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Control (2) AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good as. Tried to get an injection rate into the hor RBP at 6384'. Perf'd at 5342'. TIH with packer. Set at 55520'. RIH with 5-1/2" retainer, set at 525 to jet out retainer still could not pump thrue Milled over retainer. Tagged up on retained. Rig Release Date: Rig Release Date: TITLERegulatory Reporting (2) Remail address:laura@yatespetrolest.	swinging. s. Set packer at 5342'. Pressure test down . Hole in the casing from 5307-5342'. Pressure ole pressured up to 3000 psi. Released packer. 3307'. Pumped 30 bbls into formation and it'. TIH with stinger. Tagged up and sting into . er. Could not keep retainer in the shoe. TOOH. CONTINUED ON NEXT PAGE: Geard Date August 7, 2013
13. Describe proposed or completed opera of starting any proposed work). SEE proposed completion or recompletion. 6/24/13 – Nippled up BOP. Picked up 5-1. 6/25/13 – Set packer at 5307'. Pressure test tubing and casing from 5342' to RBP tested to 1000 psi lost 700 psi in 2 mir Tagged RBP at 6379'. Tagged up on 6/26/13 – Tagged up on RBP at 6384' and released packer. Gauge ring down to retainer. Could not pump thru. Tried 6/27/13 – Tagged up on retainer at 5257'. Spud Date: I hereby certify that the information above is trivial to the pump that the single packer. Gauge ring down to retainer. Could not pump thru. Tried 6/27/13 – Tagged up on retainer at 5257'.	Actions. (Clearly state all pertinent details, at RULE 19.15.7.14 NMAC. For Multiple Co. 1/2" AS1-X packer and TIH leaving packer st casing to 1000 psi, held good for 10 mins at 6384' to 1000 psi for 10 mins held good as. Tried to get an injection rate into the hor RBP at 6384'. perf'd at 5342'. TIH with packer. Set at 55520'. RIH with 5-1/2" retainer, set at 525 to jet out retainer still could not pump thru Milled over retainer. Tagged up on retained Rig Release Date: Rig Release Date: TITLE Regulatory Reporting	swinging. s. Set packer at 5342'. Pressure test down . Hole in the casing from 5307-5342'. Pressure ole pressured up to 3000 psi. Released packer. 3307'. Pumped 30 bbls into formation and it'. TIH with stinger. Tagged up and sting into . er. Could not keep retainer in the shoe. TOOH. CONTINUED ON NEXT PAGE: Geard Date August 7, 2013

. 1

Graham AKB State #8 Section 2-T22S-R31E Eddy County, New Mexico Page 2

Form C-103 continued:

- 6/28/13 6/29/13 Set 5-1/2" cement retainer at 5240'. Pumped 45 bbls thru tubing. Pumped 45 bb;s into perfs 3 BPM @ 1000 psi. Pressure tested casing to 500 psi, held good for 5mins. Applied 1000 psi to casing. Pumped 100 sacks Class "C" cement with 2% CaC1 followed by 100 sacks Class "C" Neat. Holed squeezed at 2450 psi. Sting out and reverse out 9 bbls of cement.
- 7/1/13 7/8/13 Tagged up on cement at 5234' and drilled retainer down to 5460'. Fell out at 5340' and circulated hole clean. Tested casing to 500 psi for 30 mins, held good. Tagged up at 6370". Work over retainer. Tagged up on RBP at 5670'. Washed sand down to RBP. Tagged up at 6379'. Tagged at 6376'.
- 7/9/13 7/16/13 Tagged at 6376'. Tagged at 5210'. Did not tag anything at 5210'. Tagged at 6376'. TIH open ended to 6375'. RIH with downhole video camera to a depth of 6375'. View area of interest at 6376'. Looks like a B valve broke and wedged. Tagged at 6377'. Released RBP at 6378'. Worked RBP thru casing collars from 6378-3952'. Worked RBP at 3952'and started pulling free. Remainder of RBP still in hole possibly at 3952'. Run magnet on wireline 2 times tagging at 3952'.

7/17/13 – 7/18/13 – Did not tag RBP at 3952'. TIH with spear to a depth of 4537'. NOTE: RBP had released and dropped down hole. TIH to a depth of 8215'. Tagged remainder of RBP. ND BOP. 2-7/8" 6.5# J-55 at 8164'.

Regulatory Reporting Technician

August 7, 2013