

10/13/2005 THU 13:21 FAX 1 432 684 3990 Dinero Companies

0002/002

10/13/2005 11:51 5053913667

PHOENIX ENVIRO

PAGE 02

Phoenix
1435 N. Fourth Dr., Hobbs, NM 88240
Phoenix
1301 W. Grand Avenue, Artesia, NM 88210
Phoenix
1080 Rio Pecos Road, Artesia, NM 87410
Phoenix
1270 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-144
June 1, 2004

For drilling and production facilities, submit to appropriate NMOCB District Office.
For development facilities, submit to Santa Fe office.

30-015-33556

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general permit"? Yes ☐ No ☒

Type of action: Registration of a pit or below-grade tank ☐ Closure of a pit or below-grade tank ☒

Operator: <u>Dinero operating</u> Telephone: <u>432-684-3356</u> Mail address: _____		
Address: <u>P.O. Box 10505 Midland Tex</u>		
Facility or well name: <u>Big Chief #2</u> API #: <u>30-015-33556</u> U/L or Q/L #: <u>5</u> Sec: <u>21</u> T: <u>22.5</u> R: <u>27.5</u>		
County: <u>Eddy</u> Latitude: <u>32° 22' 47.1"</u> Longitude: <u>104° 05' 40.9"</u> NAD: 1983 ☐ 1983 ☐		
Surface Owner: Federal ☐ State ☐ Private ☒ Indian ☐		
Pit Tank: Drilling ☒ Production ☐ Disposal ☐ Waterway ☐ Emergency ☐ Liner: ☒ Unlined ☐ Liner type: Synthetic ☐ Thickness: <u>12</u> mil Clay ☐ Pit Volume: <u>3000</u> gal		
Below-grade tank Volume: _____ gal Type of tank: _____ Construction material: _____ Double-walled, with leak detection? Yes ☐ If not, explain why not: <u>NA</u>		
Depth to ground water (vertical distance from bottom of pit to nearest high water elevation of ground water): <u>100</u> ft	Less than 50 feet 50 feet or more, but less than 100 feet <u>100 feet or more</u>	(20 points) (10 points) (10 points) <u>0</u>
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes <u>No</u>	(20 points) (0 points) <u>0</u>
Distances to surface water: (Horizontal distances to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet <u>1000 feet or more</u>	(20 points) (10 points) (10 points) <u>0</u>
Ranking Score (Total Points)		

Additional comments: (1) Attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the source box if you are burying in place) source ☒ Office ☐ If office, name of facility: _____ (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater monitoring: No ☒ Yes ☐ If yes, show depth below ground surface: _____ ft and attach sample results. (5) Attach soil sample results and a diagram of sample locations and procedures.

Additional Comments: Please see attached work plan for pit closure.

I hereby certify that the information shown is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCB guidelines ☒ as a general permit ☐ or as a collectively alternative OCB-approved plan ☐.

Date: 10-13-05
Printed Name/Title: JAMES A. DUNN, President
Your certification and NMOCB approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it release the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations.

Approval: **DENIED** Signature: **DENIED** Date: 10/13/05

This form cannot be processed due to conflicting information.

Pit registration submitted 8/10/04 lists site ranking at 10 pts.

USGS information shows this area to be water sensitive.

Please submit a plan that can be approved for a sensitive area or schedule a meeting where other water data can be reviewed.

Inspection 6/2/05 indicates Pit liner breached