<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

side of form

Form C-141

Revised October 10, 2003

Release Notification and Corrective Action

| Address: 415 West Wall St., Midland, TX 79701 Facility Name: State 32 No. 4 Telephon Facility | Garrett Donnelly e No.: 432-683-6293 Type: Oil API NO.: 30-015-25428 | |
|--|---|--|
| Facility Name: State 32 No. 4 Facility | | |
| | Type: Oil API NO.: 30-015-25428 | |
| | | |
| Surface Owner: Faulk Mineral Owner: State | Lease No.: L-6887 | |
| LOCATION OF RELEASE | | |
| Unit Letter Section Township Range Feet from the North/South Lin | ······································ | |
| F 32 22S 28E 1700 FNL | 1750 FWL Eddy | |
| Latitude l | ongitude | |
| | NATURE OF RELEASE | |
| | c of Release: 100 bbls. Volume Recovered: 75 bbls H2O / 15 bbls, Oil | |
| Source of Release: Discharge point at polyline crack due to freezing Date at | d Hour of Occurrence: Date and Hour of Discovery: | |
| conditions. Som | etime on 1/18/2014 1/18/2014 Approximately 1700 Hrs. | |
| | To Whom? Bratcher / Randy Dade | |
| By Whom? Garrett Donnelly Date at | d Hour: 1/21/2014 1600 Hrs. | |
| Was a Watercourse Reached? If YES | Volume Impacting the Watercourse. | |
| ☐ Yes X No | N/A | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| N/A | | |
| If a Watercourse was Impacted, Describe Fully.* N/A JAN 27 2014 | | |
| Describe Cause of Problem and Remedial Action Taken.* NMOCD ARTESIA | | |
| Poly flowline froze and cracked. Line has been removed and replaced with steel. | | |
| Describe Area Affected and Cleanup Action Taken.* | | |
| Discharged fluids were sucked up by a vacuum truck and deposited into the water tank on location. Contaminated soil was excavated immediately and placed onto a plastic liner for transport to R360. The excavation proceeded until dry ground was reached. The rancher mandated that no open excavated areas be left without backfilling. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| | OIL CONSERVATION DIVISION | |
| Signature 1 Ary Dog 6 | 1 | |
| | by Designed Bervilled /4 Deservice | |
| Printed Name: Garrett Donnelly | | |
| Title: Development Officer Approval | FEB 1 8 2014 Expiration Date: | |
| E PAIL II I | s of Approval | |
| | s of Approval: Glation per OCD Rule & Attached | |
| Date: January 22, 2014 Phone: 432-683-6293 Guidelines. SUBMIT REMEDIATION | | |
| PROPOSAL NO LATER THAN: 2RP-2117 | | |