


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*nTW 1402142800*

**OPERATOR**  Initial Report  Final Report

Name of Company	Oxy-Permian Ltd. <i>192463</i>	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Righthand Canyon 35-7 SWD Battery	Facility Type	Gathering

Surface Owner	BLM	Mineral Owner		API No. 30-015-34529 (nearest well)
---------------	-----	---------------	--	-------------------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	35	21S	24E					Eddy County, NM

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	800 bbls	Volume Recovered	720 bbls
Source of Release	Bad service card on PLC caused power loss to pumps so tanks spilled over	Date and Hour of Occurrence	01/01/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD, James Amos-BLM		
By Whom?	Jennifer Gilkey, BBC International	Date and Hour	01/02/2014 @ 1:58 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A bad service card on the PLC caused a power loss to the pumps causing the tanks to spill 800 bbls of produced water onto the ground. 720 bbls of produced water were recovered via vacuum truck and the service card was replaced.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area is approximately 60' x 100' on location. Remediation will be completed in accordance with a plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Christopher Jones	Approved by District Supervisor	Signed By <i>Mike Bratcher</i>	
Title: HES Specialist	Approval Date: <b>JAN 21 2014</b>	Expiration Date:	
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: <i>1/9/14</i>	Phone: (575) 628-4121	Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	

\* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**  
*February 21, 2014*

**2RP-2152**