

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
JAN 14 2014  
NMOCD ARTESIA

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

JMW1402340623 OPERATOR  Initial Report  Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Grave Digger State Com #003H	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-39151

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	2	20S	25E					Eddy

Latitude 32 36.542 Longitude 104 27.177

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	10bbls	Volume Recovered	10bbls
Source of Release	Drain line on heater treater	Date and Hour of Occurrence	01-09-2014	Date and Hour of Discovery	01-09-2014 09:30am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A hole developed in the bottom of the drain line on a heater treater. Drain heater treater and reroute the drain line while the heater treater is being repaired.

Describe Area Affected and Cleanup Action Taken.\*  
Initially 10bbls of produced water were released due to a hole that developed in the bottom of the drain line on the heater treater. We were able to recover 10bbls of produced water with a vacuum truck. The spill was contained inside the Falcon lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Robert Grubbs Jr.	Approved by District Supervisor:	Signed By
Title:	Senior Environmental Coordinator	Approval Date:	JAN 23 2014
E-mail Address:	rgrubbs@concho.com	Expiration Date:	
Date:	01-14-2014	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432-661-6601		

\* Attach Additional Sheets If Necessary

Accepted for record  
NMOCD

2RP-2156