<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

DEC 13 2013

RECEIVED

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate

NMOCD ARTESIA with Rule 116 on back

side of form

Santa Fe, NM 87505 Release Notification and Corrective Action

Oil Conservation Division

1220 South St. Francis Dr.

Name of Company BOPCO, L.P. Contact Tony Savoie Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No. 575-887-7329 Facility Name: Poker Lake Unit Well #145 (2RP-832) Facility Type Exploration and Production Surface Owner: N.M. & Federal Mineral Owner: Federal API No. 30-0/5-3100(LOCATION OF RELEASE Unit Letter Section Township Range 30 Feet from the North/South Line Feet from the East/West Line County Eddy
Facility Name: Poker Lake Unit Well #145 (2RP-832) Surface Owner: N.M. & Federal Mineral Owner: Federal LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County
Surface Owner: N.M. & Federal Mineral Owner: Federal API No. 30-0/5-3/00(LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County
<u>Latitude N 32.261914</u> <u>Longitude W 103.912095</u>
NATURE OF RELEASE
Type of Release: Produced Water and crude oil Volume of Release 10 bbls of Volume Recovered None
produced water, less than 1 bbls crude oil
Source of Release: 2 7/8 inch flow line from well #145 Date and Hour of Occurrence Date and Hour of Discovery:
6/7/11, hour unknown 6/7/11 10/15 a.m.
Was Immediate Notice Given? If YES, To Whom?
☐ Yes ☐ No ☒ Not Required
By Whom? Tony Savoie Date and Hour:
Was a Watercourse Reached? ☐ Yes ☑ No ☐ If YES, Volume Impacting the Watercourse.
If a Watercourse was Impacted, Describe Fully.*
Describe Cause of Problem and Remedial Action Taken: A 2 7/8 flow line developed a leak due to external corrosion; a repair clamp was placed on the affected area of the pipe to stop the release.
Describe Area Affected and Cleanup Action Taken.* The release happened next to a lease road and traveled across the pasture and affected an area of the half have a first and the second and traveled across the pasture and affected an area of the half have a first and the second and traveled across the pasture and affected an area of the half have a first and the second and traveled across the pasture and affected an area of the half have a first and the second and traveled across the pasture and affected an area of the half have a first and the second and traveled across the pasture and affected an area of the half have a first and the second and traveled across the pasture and affected an area of the half have a first and the second and traveled across the pasture and affected an area of the half have a first and the second and traveled across the pasture and affected an area of the half have a first and the second and traveled across the pasture and affected an area of the half have a first and the second and traveled across the pasture and the second and traveled across the pasture and affected an area of the second and the second and the second across the second and the second across the second a
approximately 2 ft. wide by 200 ft. long where it connected to an area that had been affected by several produced water spills prior to this event. The spil occurred on State land and traveled onto Federal land where it mixed with the prior releases. The total area affected by all of the releases measures
approximately 1,200 sq. ft.
Remediation activities conducted at the PLU #145 Remediation Site met the objectives set forth by the NMOCD and BLM. Soil samples collected from
the floor and sidewalls of the excavation were analyzed by an NMOCD-approved laboratory, which determined concentrations of BTEX, TPH and
Chloride were less than NMOCD Regulatory Standards. Between November 11 and 14, 2013, approximately 260 cy of impacted soil was excavated and transported to an NMOCD approximately 27 157 in width 150
transported to an NMOCD-approved disposal facility. Prior to backfilling, the final dimensions of the excavation were approximately 3'-15' in width, 150 in length and 2'-3' in depth. Please reference the attached Basin Environmental Services Technologies Remediation Summary and Site Closure.
Request for details of remediation activities.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operator are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The
acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate
and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does no relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
OIL CONSERVATION DIVISION
Signature / On Danie
Printed Name: Tony Savoie Approved by District Supervisor:
Title: Waste Mgmt. & Remediation Specialist Approval Date: 4/17/2014 Expiration Date: MA
E-mail Address: TASavoie@BassPet.com Conditions of Approval
Date: Phone: 432-556-8730 / mal