District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Revised August 8, 2011

Form C-141

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

	,		Rele	ease Notific	ation	n and Co	orrective A	ction				
Release Notification MW 1402853427 Name of Company: BOPCO, L.P. 260737 Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Facility Name: PLU-188Y The injection line spill is 630 ft. West of the well.						OPERATOR						
						Contact: Tony Savoie						
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220						Telephone No. 575-887-7329						
Facility Name: PLU-188Y The injection line spill is 630 ft. West of the well.						Facility Type: Exploration and Production						
Surface Owner: U.S.A. Mineral Owner:						: U.S.A. API No. 30-015-33776						
(Sta	0	2 Fod	(3)			N OF REI	LEASE		I			
Unit Letter C	nit Letter Section Township Range Feet from the 1				North/ No	South Line	Feet from the 1270			County: Eddy		
							le <u>W 103.90815</u>					
				NAT	URE	OF REL			Production API No. 30-015-33776 St/West Line County: Eddy Volume Recovered: 30 bbls. Date and Hour of Discovery: 1/10/14 at 12:30 p.m. The BLM D.M. Watercourse. PRECEIVED JAN 15 2014 AIMOCD ARTESIA AIMOCD ARTESIA			
Type of Release: Produced water Source of Release: 3" fiberglass high pressure flow line												
Source of Release: 3 Thergiass fight pressure flow line						1/10/14 Ti	•					
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? NMOCD emergency #104 and the BLM						
By Whom? Tony Savoie						Date and Hour: 1/10/14 at 3:41 p.m.						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
If a Westernson		<u></u>							TD		VEI	7
If a Watercou	irse was im	pacied, Descri	ibe Fully.	•					1 17	LUEI	VEL	
										JAN 15	2014	
Describe Cau	se of Proble	em and Remed	dial Actio	n Taken.*					NIM	OCD A	TES	31 /
The fiberglas	s injection l	ine ruptured,	cause unk	nown. The line se	gment v	vas isolated u	ntil the section of	line can	be replace	ed		
		and Cleanup A										
received at 2:	00 p.m. on	1/14/14. Crew	s will star	rt removing the im	pacted	soil when the		CHIHSSIO	i to start i	cinoving co	mannin	ttion was
The remediat	ion will con	nply with the	NMOCD	and BLM remedia	ation gu	idelines.	•					
I hereby certi	fy that the i	nformation gi	ven above	is true and compl	lete to th	ne best of my	knowledge and u	nderstand	d that purs	suant to NM	OCD ru	les and
should their o	perations h	ave failed to a	dequately	investigate and re	emediate	e contaminati	on that pose a thre	eat to gro	und wate	r, surface wa	ater, hur	man health
				otance of a C-141 i	report d	oes not reliev	e the operator of t	responsib	ility for c	ompliance v	vith any	other
federal, state, or local laws and/or regulations.						OIL CONSERVATION DIVISION						
Simulation												
Signature: 1 om Smuu						Approved by Environmental Specialistined By						
Printed Name	Tony Save	oie				Environmentar sp	occian per	ned By	101114	() KART	ness.	
Title: Waste N	Managemen	t and Remedi		JAN 28 2014 Approval Date: Expiration Da				Date:				
E-mail Address: tasavoie@basspet.com						Conditions of Approval:				Attached		
Doto:	14/14		422 556 9520	Re	lemediation per OCD Rule & Guidelines, &							
Date: // Attach Addit	· · ·	ts If Necess		432-556-8730	_ like	approval by	BLM. SUBMITER	REMEDIA	TION	OPO	011	
ruult	.onai onec	11 11 1000336	~• J		Z	PROPO	SAL NO LATER T	HAN:		ZNP-	-211	9 1
					-/-*	Pruare	y 50, 50	47				



