District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

614

10.00

No. of Street, or

「「「「

国家語

A TANK

4.4

語言の

## State of New Mexico **Energy Minerals and Natural Resources**

**Oil Conservation Division** 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## **Release Notification and Corrective Action**

	OPERATOR	Initial Report	$\boxtimes$	Final Report
Name of Company Linn Operating	Contact Brian Wall			
Address 2130 W. Bender, Hobbs, NM 88240	Telephone No. (806) 367-0645			
Facility Name HE West B # 2 Battery / West B #88	Facility Type Battery			

Surface Owner Federal

Mineral Owner Federal

3001528537 API No.

## **LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	09	175	3'1E	1309	North	1310	West	Eddy

Latitude\_32.85273\_\_\_ Longitude\_-103.87827\_

## NATURE OF DELEACE

NATURE OF RELEASE						
Type of Release Oil / Produced Water	Volume of Release 8/2	Volume Recovered 0/0				
Source of Release Valve	Date and Hour of Occurrence	Date and Hour of Discovery 06/07/2012				
· · · · · · · · · · · · · · · · · · ·	06/07/2012 8:30am	9am				
Was Immediate Notice Given?	If YES, To Whom?	· · · · · · · · · · · · · · · · · · ·				
🗌 Yes 🛛 No 🗌 Not Required	d M. Bratcher – NM OCD Terry Gregston - BLM					
By Whom? Joe Hernandez Date and Hour 06/13/2012						
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.					
Yes X No						
If a Watercourse was Impacted, Describe Fully.*						
Describe Cause of Problem and Remedial Action Taken.* 2" T on the production header was buried and failed releasing oil and produced water.						
Describe Area Affected and Cleanup Action Taken.* The release affected 17,545 sq ft of battery and pasture land. Two other environmental companies worked						
this site previously to RECS taking over remediation activities. When RECS obtained the site, the battery had already been excavated to 1.5 - 3 ft bgs and a request						
to backfill the site had been approved by BLM on July 26th, 2013. As part of permission to backfill, BLM had a stipulation that Sample Point 1 needed to be						
delineated to find closure levels. The site was backfilled and contoured to the surrounding location. RECS took over the project on August 27 <sup>th</sup> , 2013. A vertical						
was attempted at Point 1 on September 17 <sup>th</sup> , 2013; however, installation was aborted when a fiberglass line was found below Point 1. On September 20 <sup>th</sup> , 2013,						
RECS met with NMOCD and NMOCD stated that RECS needed to assess the release outside the bermed battery area. On September 25 <sup>th</sup> , 2013, RECS met with						
BLM and BLM stated that the work was completed inside the battery and RECS needed to assess the release outside the battery. RECS sampled that area outside the battery on bacing on Ostober 8 <sup>th</sup> 2013. Samples uses the surface of assess the release outside the battery and area outside the battery on bacing an Ostober 8 <sup>th</sup> 2013.						
the battery on beginning on October 8 <sup>th</sup> , 2013. Samples were taken from the surface at seven points within the release area outside the bermed battery and one sample, Point 7, was taken as background sample. The samples were field tested for chlorides and organic vapors and the samples were taken to a commercial						
laboratory for analysis. All the samples returned chloride values below 1,000 mg/kg, GRO values of non-detect and DRO values below regulatory standards, except						
for the background sample at Point 7, which returned a DRO value of 5,890 mg/kg. A Corrective Action Plan (CAP) was submitted to NMOCD and BLM on						
December 5 <sup>th</sup> , 2013. BLM approved the CAP on December 6 <sup>th</sup> , 2013 and NMOCD approved the CAP on February 11 <sup>th</sup> , 2014. As a stipulation for approval of the						
CAP, NMOCD requested that since this release encompasses another release at the site, a final C-141 for the 2RP-950 be enclosed with the final documentation for						
his site. RECS personnel were on site on February 24th, 2014 to conduct the CAP work. Soil amendments were added to the site and the site was seeded with						
BLM mix #2 and #4. The remainder of the contamination from the release will be addressed at site abandonment.						

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

	OIL CONSERVATION	DIVISION
Signature: Fred B Wall		$\cap$
Printed Name: Brian Wall	Approved by Environmental Specialist:	Vin
Title: Construction Foreman II	Approval Date: 5/1/4/14/ Expiration I	Date: NA
E-mail Address: Bwall@linnenergy.com	Conditions of Approval:	Attached
Date: 4-4-14 Phone: (806) 367-0645	Fnal	
Attach Additional Sheets If Necessary		ZRP-1189