| | strict I 25 N. French Dr., Hobbs NECEIVED Energy Minerals and Natural Resources | | Form C-141 Revised August 8, 2011 | | |
|-------------|---|--|--------------------------------------|-------------------------------------|--|
| | 811 S. First St., Artesia, NM 88210 District III JÁN 08 2014 Oil Com | servation Division | Submit I Cop | y to appropriate District Office in | |
| _ | 1000 Rio Brazos Road, Aztec. NM 87410 <u>District IV</u> 1220 South St. Francis Dr. | | ຄ | ccordance with 19.15.29 NMAC. | |
| | | | | | |
| <u>1993</u> | Release Notificat | ion and Corrective A | Action | | |
| | Nome of Company, Ling Operating | OPERATOR Contact Brian Wall | Init | ial Report 🛛 Final Report | |
| 闧 | Name of Company Linn Operating Address 2130 W. Bender Blvd., Hobbs, NM 88240 | | Telephone No. (806) 367-0645 | | |
| | Facility NameH.E. West B #85Facility Type | | Producer | | |
| | Surface Owner Federal Mineral Own | er | API No. 3001528387 | | |
| | LOCAT | ION OF RELEASE | | | |
| | Unit Letter Section Township Range Feet from the No | orth/South Line Feet from the | East/West Line | County | |
| 225 | K 3 17S 31E 2614 | South 2621 | West | Eddy | |
| | Latitude_32.86357 | Longitude103.85696 | | | |
| | NATU | RE OF RELEASE | | | |
| Ω. | Type of Release Oil | Volume of Release 5 gal | | Recovered 0 | |
| | Source of Release Poly Pipeline | Date and Hour of Occurrer 8/18/2013 8:30 am | ce Date and 8:30 am | Hour of Discovery 8/18/2013 | |
| ्रज्य | Was Immediate Notice Given? | If YES, To Whom? red Mike Burton - BLM | | | |
| | By Whom? Brian Wall Date and Hour 8/19/2013 2:00 pm | | | | |
| | Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. | | | | |
| | If a Watercourse was Impacted, Describe Fully.* | | | | |
| 緻 | | | | | |
| Ŋ | Describe Cause of Problem and Remedial Action Taken.* 150' from the well head on the road leading into the location, a pin hole in the flow line developed. The W. #85 and WB #56 share the same flow lines and the wells were shut in until repairs could be made. Possible line fatigue. | | | | |
| | Describe Area Affected and Cleanup Action Taken.* A total of 5 gallo | ons of oil was sprayed over 7,402 sq f | t. RECS personnel w | vere on site beginning on August | |
| | 21 st , 2013 to assess the site. Samples from the surface and at depth were taken from five points throughout the release and representative samples from three of the points were taken to a commercial laboratory for analysis. Laboratory chloride levels dropped to below regulatory standards by 1 ft bgs at Pt. 1, by 6 inches at Pt. 2 and by 1.5 ft at Pt. 3. Gasoline Range Organics (GRO) and BTEX were non-detect at all points and all depths. Diesel Range Organics (DRO) were present at all points at the surface but dropped to non-detect at all depths below the surface. A Corrective Action Plan (CAP) was submitted to BLM to NMOCD on September 20 th , 2013 and was approved by BLM on September 23 rd , 2013 and by NMOCD on October 10 th , 2013. On September 23 rd , 2013, BLM suggested that if RECS scraped only 6 inches, the soil remaining on site could be blended and countered to use as backfill, rather than importing soil. CAP activities began on October 29 th , 2013. The release was scraped to a depth of 6 inches bgs and a total of 68 yards of soil was taken to a NMOCD approved facility for disposal. At the base of the scrape a 5 point bottom composite was obtained and set to a commercial laboratory for analysis. The 5 point bottom composite returned a chloride result of 124 mg/kg GRO and DRO results of non-detect and a BTEX result of 0.483 mg/kg. A total of 24 yards of caliche was imported to the site to backfill the lease road. A sample of the caliche was taken to a commercial laboratory and returned a chloride result of non-detect. On November 4 th , 2013, BLM and NMOCD approved the final laboratory sampling and allowed the site to be backfilled. The pasture area was | | | | |
| | | | | | |
| n | | | | | |
| | | | | | |
| _ | | | | | |
| | contoured with the remaining soil on site and the lease road was backfilled with the imported caliche. On November 14th, 2013, soil amendments were added to the pastu area and the site was seeded with LPC mix. | | | | |
| | nereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and | | | | |
| | regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endang public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liabil | | | | |
| 1 | should their operations have failed to adequately investigate and remect or the environment. In addition, NMOCD acceptance of a C-141 report | | | | |
| 1 | federal, state, or local laws and/or regulations. | · · · · · · · · · · · · · · · · · · · | · · · | | |
| | Trad Phiall | OIL CONSERVATION DIVISION | | | |
| ł | Signature: Fred B Wall | | | | |
| ļ | Printed Name: Brian Wall | Approved by Environmental S | | m | |
| | Title: Construction Foreman II | Approval Date: 5/15/14 | 1 Expiration I | Date: NA | |
| | E-mail Address: Bwall@linnenergy.com | Conditions of Approval: | 0 | Attached | |
| | Date: 1-8-14 Phone: (806) 367-0645 | Fin. | X | | |
| * | Attach Additional Sheets If Necessary | ······································ | | RP-1865 | |