

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nHMP1416429096		<b>OPERATOR</b> <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report	
Name of Company Devon Energy Production 6137		Contact Tracy Kidd -Production Foreman	
Address PO Box 250 Artesia, NM 88210		Telephone No. 575.513.0628	
Facility Name Ross Ranch 10 Fed 1 SWD		Facility Type Salt Water Disposal	
Surface Owner Federal		Mineral Owner Federal	API No. 30-015-29605

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	10	26S	31E	1980	North	660	East	Eddy

Latitude: 32.059235486

Longitude: -103.75905787

**NATURE OF RELEASE**

Type of Release Spill Produced Water	Volume of Release 1300BBLs in lined containment- 4BBLs on ground	Volume Recovered 1303BBLs
Source of Release hole in lined containment	Date and Hour of Occurrence 6/9/2014 10:29AM	Date and Hour of Discovery 6/9/2014 10:29AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos-BLM & Thomas Oberding-OCD	
By Whom? Lynn Smith; Assistant Production Foreman	Date and Hour 6/10/2014 10:00AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

A pin hole in the lined containment formed causing the spill that escaped containment. After the produced water was recovered it was discovered that the 6" fiberglass fill line had come apart at a tee on the bottom section causing the spill into the lined containment. Containment will be repaired. Braces will be built on fill line. Spill occurred on the south side of the pad affecting approximately 28'x160'.

**NM OIL CONSERVATION**  
ARTESIA DISTRICT


Describe Area Affected and Cleanup Action Taken.\*

Equipment will be steam cleaned and affected soil will be removed and replaced with fresh soil.

JUN 12 2014

**RECEIVED**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sandra Farley	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Sandra Farley	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 6/13/14	Expiration Date: NA
E-mail Address: Sandy.Farley@dvn.com	Conditions of Approval: remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: June 10, 2014	Phone: 575.746.5587	

\* Attach Additional Sheets If Necessary

**PROPOSAL NO LATER THAN:**

7/13/14

2RP-2342