
Submit I Copy To Appropriate District Office	State o	f New Me	xico			Form C-103
District I – (575) 393-6161	Energy, Mineral	ls and Natu	ral Resources			sed August 1, 2011
1625 N. French Dr., Hobbs, NM 88240				WELL API		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-015-02984		
<u>District III</u> – (505) 334-6178		th St. Fran		5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410				STAT		
<u>District IV</u> – (505) 476-3460	Santa	Fe, NM 87	7303		& Gas Lease N	√ 0.
1220 S. St. Francis Dr., Santa Fe, NM 87505				E-4200		
	TICES AND REPORTS OSALS TO DRILL OR TO DE			7. Lease Na	me or Unit Ag	reement Name
DIFFERENT RESERVOIR. USE "APPL	ICATION FOR PERMIT" (FC	ORM C-101) FC	OR SUCH	CONTINEN	TAL STATE	
PROPOSALS.)	Con Wall			8. Well Nun		
1. Type of Well: Oil Well X	Gas well Other			001		
2. Name of Operator COG OPERATING LLC		···		9. OGRID N 229137	lumber	
3. Address of Operator					ne or Wildcat	
600 W. ILLINOIS AVE., MIDLA	ND. TEXAS 79701			1	G-JACKSON;	ONS.A.
		-,				
4. Well Location						
Unit Letter; N ;	660 feet from the	SOUTH		feet from the		ne
Section 15	Township		Range 29E	NM	PM EDDY	County
	11. Elevation (Show)	whether DR, 3,565' –)		
12 (1 1	A	<u> </u>		D	d. D.	
12. Check	Appropriate Box to	indicate N	ature of Notice,	Report or O	iner Data	
NOTICE OF I	NTENTION TO:		SUB	SEQUENT	REPORT	OF:
PERFORM REMEDIAL WORK □	_	N X	REMEDIAL WOR			NG CASING □
TEMPORARILY ABANDON			COMMENCE DR			
PULL OR ALTER CASING		Ä	CASING/CEMEN		<u>-</u>	•
DOWNHOLE COMMINGLE		Ш	O/ CONTO/ OEMIEN			
DOWN IOLE COMMINGLE						
OTHER:		П	OTHER:			
13. Describe proposed or com	pleted operations. (Clear	rly state all r	L	d give pertinen	t dates, includ	ing estimated date
of starting any proposed w						
proposed completion or re		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	o. Tot manipie co	inprocions. 7 ktd	aen weneere e	nugrum or
proposed completion of re	completion.					
1) SET 5-1/2" CIBP @ 2,350) ² PUMP 25 SXS_CMT	@ 2 350'-2	2.230' (S.A. PERES	9		
2) SET 5-1/2" CIBP @ 1,050					C. WELL W/	PXA MUD
3) PUMP 35 SXS. CMT. @ 4					0. 1. 222 11.	
4) PERF. X ATTEMPT TO						
5) DIG OUT X CUT OFF W					ALL DRY H	OLE MARKER.
5) 2.0 001 /1 001 01. 11	DEELIERID 3 D.O.D.,	, 222 0				
DURING THIS PROCEDURE WE	E PLAN TO USE THE C	LOSED-LO	OP SYSTEM W/	A STEEL TAN	K AND HAU	L CONTENTS
TO THE REQUIRED DISPOSAL,						
,				AL ATTACHED		
		Annro	val Granted area	ا بامانی	MOIL	CONSERVATION
Spud Date:	Rig	1 22	val Granted prov	iding work is	ARTE	ESIA DISTRICT
		Comp	leted by	2015		1 / 201/
			0 /2	0013	JU	L 1 4 2014
I hereby certify that the information	above is true and comp	lete to the he	est of my knowledg	e and belief		
Thereby certify that the information	above is true and comp	icte to the oc	ist of my knowledg	e and belief.	Ŕ	ECEIVED
~	\cdot () $_{-}$,	
SIGNATURE_	N. 2 D TI	TLE: AGE	NT		DATE: 07/0	7/14
Type or print name: DAVID A. EY	LER E-mail ac	ddress: DEY	LER@MILAGRO	-RES.COM	PHONE: 432	2.687.3033
For State Use Only	•					
	$\mathcal{A}_{\mathbf{A}}$	1	775 m		_	
APPROVED BY: (1)	TIT TIT	LE Ocsa	MXXXIVI.	50)	_DATE_&_	12.2014
Conditions of Approval (if any):						···
- 4	11001:					

* See A Hacked COA'S

_					
-	m	١,	ኅ	11	e
_			•	,	•

	Location:
Footage:	660 FSL & 1980 FWL
Section:	15
Township:	17S
Range:	29E
County:	Eddy County, NM
	Elevations:
GL: KB:	
KB:	12
	Pumping Unit:
Unit Size:	
Speed:	

Continental St #1



NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: CO 6	·	
Well Name & Number: Continental	State	at
API#: 30-015-02984		

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 1 year of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 3. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 8-12-2014

APPROVED BY: Dale

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).