

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION State of New Mexico
ARTESIA DISTRICT Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

AUG 21 2014

RECEIVED

Release Notification and Corrective Action

N HMP 142 3354263

OPERATOR Initial Report Final Report

Name of Company Devon Energy Production <i>10/31</i>	Contact Tracy Kidd
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-513-0628
Facility Name Cotton Draw Unit 65 SWD	Facility Type Salt Water Disposal

Surface Owner Federal	Mineral Owner State	API No. 30-015-10843
-----------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	2	25S	31E	1980	N	1980	E	Eddy

Latitude: 32.161085918

Longitude: -103.746039442

NATURE OF RELEASE

Type of Release Spill produced water	Volume of Release 30BBLS	Volume Recovered 10BBLS
Source of Release produced water line	Date and Hour of Occurrence 8/15/2014 4:30 PM	Date and Hour of Discovery 8/15/2014 4:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM- Jeff Robertson & OCD- Thomas 'Doc' Oberding	
By Whom? Joah Weidemann, Assistant Production Foreman	Date and Hour 8/18/2014 @ noon	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Leak was on the header section on the east side of Cotton Draw Unit 65 Salt Water Disposal battery where the Cotton Draw Unit 86 water ties in. The line had been isolated but was opened on 8-14-14 to perform flowback to the Cotton Draw Unit 86. The leak was on a 4" steel section of pipe where the exposed threads were corroded. ON 8-15-15 the line was isolated and a vacuum truck was called out to recover the spilled water. The corroded section of pipe has been replaced.		
Describe Area Affected and Cleanup Action Taken.* Vacuum truck recovered 10BBLS of produced water spilled. Area affected was approximately 200'x15' on the caliche pad. The produced water flow headed south about 30' and turned west approximately 200'. The leak appeared to be approximately 20' wide at the greatest area. Talon LPE will be collecting soil samples to determine the specific cleanup remedies necessary.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sandra Farley</i>	OIL CONSERVATION DIVISION	
Printed Name: Sandra Farley	Approved by <i>Mike Brannan</i> Signed By Environmental Specialist:	
Title: Field Admin Support	Approval Date: <i>8/21/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>Sandy.Farley@dvn.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	
Date: 8/18/14 Phone: 575.746.5587	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

9/21/14

2RPA452