
Submit 1 Corry To Appropriate District Office	State					Form C-103	
District 1	State of New Mexico <u>trict 1</u> Energy, Minerals and Natural Resources		esources	Revised August 1, 2011			
1625 N. French Dr.,Hobbs, NM 88240 District II	i. French Dr.,Hobbs, NM 88240			30-015-39021			
811 A. First St., Artesia, NM 88210	First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		VISION	5. Indicate Type of Lease			
<u>Disrtict III</u> 1000 Rio Brazos Rd. Aztec, NM 87410	d. Aztec, NM 87410 1220 South St. Francis Dr.		Dr.	STATE 🗹 🛛 FEE 🗌			
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505				6. State Oil & Gas Lease NO.			
		······				07-0002	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				7. Lease Name or Unit Agreement Name Empire Abo Unit		-	
PROPOSALS.)					8. Well Number		
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator					411 9. OGRID Numer		
Apache Corporation					873		
3. Address of Operator 303 Veterans Airpark La	ane, Ste. 3000, Midlan	d, TX 79705		10. Pool N		bo (22040)	
4. Well Location	40	. NI		4.4.5			
Unit Letter D Section 6	: 40 feet from t Township 18S	he No. Range	line and 28E	145 NMPM	feet from the	W line County Eddy	
	1. Elevation (Show whethe	er DR, RKB,RT,					
		3664' GR	· .		L	с <u>ь.</u> у	
12. Check A	Appropriate Box To Indi	cate Nature of	Notice, Rej	port, or Ot	her Data		
NOTICE OF IN	TENTION TO:			SUBSEQ	UENT REP	ORT OF:	
	PLUG AND ABANDO	N []	REMEDIAL				
TEMPORARILY ABANDON	CHANGE PLANS MULTIPLE COMPL		COMMENC CASING/CE		- · ·		
DOWNHOLE COMMINGLE			ALTERING		י נ [
			P AND A		[
OTHER:			OTHER:				
13. Describe proposed or completed opera any proposed work.) SEE RULE 110							
CONDITIONS OF APPROVAL ATTACHED		Approved for plug	ting of well bore	oniv.	ר		
Approval Granted providing work is		Liability under bor	id is retained pe	nding receipt			
Completed by		of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page-under					
Oct 30, 2015 Forms, www.cmnrd.state.nr			.state.nm.us/occ	ł.	_		
Apache Corporation proposes to P	&A the above mention	ned well by th	e attached	procedu	re. A close	d loop system will	
	s from this wellbore a						
					NM	OIL CONSERVATION ARTESIA DISTRICT	
						OCT 3 0 2014	
Spud Date:		Rig Releas	se Date:				
		-				RECEIVED	
I hereby certify that the information above is true	and complete to the best of f	my knowledge and	d belief.				
SIGNATURE Sunn	Burks_TITLE	Sr. Rec	lamation Fo	oreman	DATE _	10/23/14	
Type or print name Guinn	Burks E-mail ac	ld. <u>guinn.burl</u>	<u>ks@apache</u>	corp.com	PHONE:	432-556-9143	
For State Use Only APPROVED BY: Conditions of Approval (if any):		Dist	FS ye	wrsn	DATE	00+ 30,2014	
A See Attach	hed COA's						

-



		a an	
No.			Empire Abo Unit
4		WELL #	411
	ADDEME	API # COUNTY	
	WELL BORE INFO.		PROPOSED PROCEDURE
0			
	11'' Hole 8 5/8'' 24# @ 500'		 PUH & spot 55 sx Class "C" cmt from 550' to surf. (Yates & Surface Shoe)
631	w/ 310 sx to surf		
031			
			4 DILL 9, and 25 av Class "O" and from 1101 960
			4. PUH & spot 35 sx Class "C" cmt from 1191'-869' (Queen & 7 Rvrs)
1262			
1894			3. PUH & spot 45 sx Class "C" cmt from 1986'-1545'
			WOC/TAG (Grayburg/San Andres)
2525			·
	DV TOOL @ 3036' w/ 544 sx to surf		
3156			
			2. PUH & spot 55 sx Class "C" cmt from 3533'-2986'
			WOC/TAG (Glorieta, Yeso, & DV Tool)
3787			
4418			
5050			
5681			1. MIRU, RIH & verify CIBP @ 5726', CIRC w/MLF & spot 35 sx Class "C" cmt from 5726'-5370' WOC/TAG
Г	While drilling, left 432' of fish in the hole. Spotted 225 sx, kicked		(Abo)
L	off and continued to TD		CIBP @ 5726' w/ 35' cmt ABO perfs @ 5774'-5938'
	7 7/8" Hole 5 1/2" 17# @ 6312' w/ 552 sx		-
6312	DVT set @ 3036' w/ 544 sx to surf	PBTD @ 5726' TD@ 6312'	

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT
Operator: Apache
Well Name & Number: Empire ABO Unil 4/1
API #: 30-015-39021

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 1 year of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
10. Plugs may be combined after consulting with and getting approval from NMOCD.
11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 10/30/2014

APPROVED BY: SP

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - o Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).