

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

MAY 08 2013

Form C-141
Revised October 10, 2003

NMOC D ARTESIA

Submit copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1312 855239

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company : Oxy Permian LTD (192463)	Contact : Chris Jones
Address : 1502 W. Commerce, Carlsbad, NM 88220	Telephone No. : 575-628-4121
Facility Name : North Burton Flats Battery	Facility Type: Central Tank Battery
Government AA COM #2	
Surface Owner : Federal	Mineral Owner
API#: Lease #: NM 18293	

LOCATION OF RELEASE

30-015-33283

Unit Letter D	Section 23	Township 20S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release : Produced Fluids	Volume of Release : 40 bbls	Volume Recovered: 10 bbls
Source of Release : Heater Treater	Date and Hour of Occurrence: 3/17/2013 7:00 am	Date and Hour of Discovery: 3/17/2013 7:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD/Mike Bratcher & BLM/Jim Amos	
By Whom: Jonathan Haver 575-706-9249	Date and Hour : 3/18/2013 2:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A flange leaked on the heater treater causing a release of 40 barrels of produced fluids. The heater treater was taken out of service, repaired and put back into production. A vac truck was immediately called to the location and recovered 10 barrels of produced fluids.

Describe Area Affected and Cleanup Action Taken.* The area impacted measured approximately 10'x60' around the heater treater. Talon/LPE has been contracted to complete site assessment and remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Chris Jones

Title: HES Specialist

E-mail Address: Christopher Jones@oxy.com

Date: 3/18/2013 Phone: 575-628-4121

Approved by District Supervisor:

Signed By

MAY 08 2013

Approval Date:

Expiration Date:

Conditions of Approval:

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

June 8, 2013

Attached ☐

2RP-1649

* Attach Additional Sheets If Necessary