

NM OIL CONSERVATION

ARTESIA DISTRICT

State of New Mexico
Energy Minerals and Natural Resources

FEB 06 2015

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Devon Energy Production Co LP (6137) <i>6137</i>	Contact: Mike Palmer, Consultant
Address: PO Box 250 Artesia, NM 88211	Telephone No. 575-420-2711
Facility Name: Cotton Draw Unit 206H	Facility Type: Well location

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42072
-------------------------------	-------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	26	24S	31E	150	South	1400	East	Eddy

Latitude: ___ Longitude: ___

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 12 bbls	Volume Recovered: 0 bbl
Source of Release: Dart Valve	Date and Hour of Occurrence 2/4/15, 1:50 PM	Date and Hour of Discovery 2/4/15, 1:50 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Mike Bratcher BLM-Jeff Robertson	
By Whom? Denise Menoud, Field Tech	Date and Hour: 2/4/2015, 2:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
Halliburton was performing the fracture treatment on Stage 16 when a check valve (dart valve) washed out causing the spill. The water immediately soaked in the ground so a vacuum truck was not used.

Describe Area Affected and Cleanup Action Taken.*
20' x 40'. Since the water soaked into the ground instantly, immediate cleanup was not possible.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Signed By <i>Mike Bratcher</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	Approval Date: 2/10/15 Expiration Date: N/A
E-mail Address: Denise.Menoud@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/5/2015 Phone: 575-746-5544	Remediation per O.C.D. Rules & Guldellnes SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>3/10/15</u>	

2BP-2798