

	•	
State of New Mexico	Form C-103	
District I – (575) 393-MM OIL CONSERVATE M. Minerals and Natural Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NMRSENIA DISTRICT	WELL API NO.	
District II - (575) 748-1283 811 S. First St., Artesia, NM 884 B 1 7 2015 OIL CONSERVATION DIVISION	30-015-32715 5. Indicate Type of Lease	
District III - (505) 334-6178 1220 South St. Francis Dr.	STATE STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 DECETIVED Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM		
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Louis raine of other agreement raine	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	HB2STATE	
1. Type of Well: Oil Well Gas Well Other	8. Well Number	
,, <u> </u>	0.0GRID Number	
Name of Operator Devon Energy Production Company, LP	9. OGRID Number 6137	
3. Address of Operator	10. Pool name or Wildcat	
333 W. Sheridan Avenue, Oklahoma City, OK 73102	CEDAR CANYON; BONE SPRING	
4. Well Location		
Unit Letter M : 660' feet from the South line and 660'	feet from theWestline	
Section 02 Township 24S Range 29E	NMPM Eddy County, NM	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3068' KB; 3051'GL; 17' KB to GL		
	Daniert en Other D. (
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WOR		
TEMPORARILY ABANDON	LLING OPNS. 🗌 PAND A 🔀	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	「JOB □	
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM	П	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	I give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Con	npletions: Attach wellbore diagram of	
proposed completion or recompletion.		
1. MIRU. POOH w/ 2-7/8" production tubing from 8,394'.		
2. RIH set CIBP @ 7,900'. Dump bail 35' CL H cement on top. PBD @ 7,865'		
3. TOH to 6,850'. Spot 50 sx (150') CL C balanced plug.		
4. TOH to 5,000'. Spot 50 sx (150') CL C balanced plug. 5. TOH to 3,150'. Spot 100 sx (1200') CL C balanced plug. WOC PIH and tog TOC	(CTOC @ 2850' 0.5/8" -L @ 2072'	
5. TOH to 3,150'. Spot 100 sx (300') CL C balanced plug. WOC. RIH and tag TOC Delaware Top @ 3106'. Base of Salt @ 2894'.)	(C10C @ 2030 . 9-3/8	
6. TOH to 700': Spot 100 sx (300') CL C balanced plug. WOC. RIH and tag TOC (C	TOC @ 400'. 13-3/8" shoe @ 540', Top of	
Salt @ 615')		
7. TOH. Spot 25 sx Cl C 60' to surface.	Approved for plugging of well bore only. Liability under bond is retained pending recei	
8. Cut wellhead off and set dry hole marker.9# mud will be circulated between each plug.	of C-103 (Subsequent Report of Well Plugging	
CONDITIONS OF APPROVAL ATTACHED	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.	
Approval Granted providing work is		
Completed by Rig Release Date:		
9eb 18 th , 2016		
I hereby certify that the information above is true and complete to the best of my knowledge	and belief.	
	•	
SIGNATURE Male A BI- A TITLE OF THE	DATE 2/12/2015	
SIGNATURE Man Dad TITLE Operations Technician	DATE 2/12/2019	
Type or print name Michael Blad E-mail address: _Michael.Blad@dvn.com PH	ONE: _405-552-8077	
For State Lise Only		
APPROVED BY: SILL WALL THE DIST HE MONNIE	DATE 2/18/2015	
APPROVED BY: See A Hacked COA'S	DATE NITO COLO	
* Jee H Hacked WAS		





NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Devon			<u> </u>
Well Name & Number: H B	2	State	#3
API#: 015 - 327/5			

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.

11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 2/18/2015

APPROVED BY SOL

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).