

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

Form C-141
MAR 9 2015 Revised August 8, 2011
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1506928926		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P.		2100737			
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Contact: Tony Savoie			
Facility Name: PLU-212, the leak is 1350 east of the well on the north edge of the PLU-213 Tank Btry. And SWD		Telephone No. 575-887-7329			
		Facility Type: Exploration and Production			
Surface Owner: Federal		Mineral Owner: Federal		API No. 30-015-33915	

LOCATION OF RELEASE

Unit Letter P	Section 18	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.212869 Longitude W 103.914300

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 6 bbls crude oil and 6 bbls produced water	Volume Recovered: None
Source of Release: 27/8" flow line	Date and Hour of Occurrence: 3/4/15 time unknown	Date and Hour of Discovery: 3/14/15 at approximately 5:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The flow line developed a leak due to external and internal corrosion. An emergency repair clamp was placed on the leak area. On 3/5/15, two joints of pipe were replaced.		
Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 1050 sq. ft. of pasture area just north of the PLU-213 Tank battery and SWD. The spill location is near the re-vegetated area from the original reserve pit. All of the fluid soaked into the ground. The stained area was left as is pending the final remediation. There is an on-going remediation plan being developed for the pad and surrounding area.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: Tony Savoie		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: [Signature]	
Title: Waste Management and Remediation Specialist		Approval Date: 3/10/15	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com		Conditions of Approval:	
Date: 3/9/15 Phone: 432-556-8730		Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
		SUBMIT REMEDIATION PROPOSAL NO	
		LATER THAN: 4/10/15	

* Attach Additional Sheets If Necessary

2RP-2871