Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NM ONCOUNSERVATION ARTESIA DISTRICT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS FAR 0 2 2015

5. Lease Serial No. NMLC061705A

Do not use the abandoned we	6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or No. 891000303E	
1. Type of Well Gas Well O	ther		8. Well Name and No. POKER LAKE UNIT 078	
2. Name of Operator Contact: TRACIE J CHERRY BOPCO LP E-Mail: tjcherry@basspet.com			9. API Well No. 30-015-27536	
3a. Address P O BOX 2760 MIDLAND, TX 79702		3b. Phone No. (include area code) Ph: 432-221-7379	10. Field and Pool, or Exploratory POKER LAKE; DELAWARE SW	
4. Location of Well (Footage, Sec.,	11. County or Parish, and State			
Sec 25 T24S R30E NENE 66	60FNL 660FEL		EDDY COUNTY, NM	
12. CHECK APP	ROPRIATE BOX(ES	S) TO INDICATE NATURE OF NO	OTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION			
	□ Acidize	□ Deepen	□ Production (Start/Resume) □ Water Shut-Off	

TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Notice of Intent ☑ Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair	☐ Deepen ☐ Fracture Treat ☐ New Construction	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete	☐ Well Integrity ☑ Other	
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☐ Plug and Abandon☐ Plug Back☐	□ Temporarily Abandon□ Water Disposal	Venting and/or Flari	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BOPCO, LP respectfully submits this sundry notice to report the volume flared for 90-days on the referenced agreement. Wells contributing to the flaring volume are as follows:

Lease number/well/API

NMLC061705B / POKER LAKE UNIT 100 / 30-015-27961-00-S1 NMLC061705B / POKER LAKE UNIT 103 / 30-015-27919-00-S1 State - E2206 / POKER LAKE UNIT 105 / 30-015-27895-00-S1 NMLC061705B / POKER LAKE UNIT 106 / 30-015-27920-00-S1 NMNM0157779 / POKER LAKE UNIT 108 / 30-015-28086-00-S1 NMNM0157779 / POKER LAKE UNIT 111 / 30-015-28087-00-S1 State - B10685 / POKER LAKE UNIT 114 / 30-015-28102-00-S1

	The state of the s				
14. I hereby certify that the foregoing is true and correct. Electronic Submission #222915 verified by the BLM Well Information System For BOPCO LP, sent to the Carlsbad Committed to AFMSS for processing by JUNE CARRASCO on 10/29/2013 ()					
Name (Printed/Typed)	TRACIE J CHERRY	Title	REGULATORY ANALYST		
Signature	(Electronic Submission)	Date	10/14/20 ACCEPTED FOR RECORD		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved By		Title	// FEB Zn 2013		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE		
The second of the second secon					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #222915 that would not fit on the form

32. Additional remarks, continued

STATE - B10685 / POKER LAKE UNIT 115 / 30-015-28180-00-S1 NMLC061705A / POKER LAKE UNIT 118 / 30-015-29213-00-S1 NMLC061705A / POKER LAKE UNIT 78 / 30-015-27536-00-S1 NMLC061705A / POKER LAKE UNIT 80 / 30-015-27537-00-S1 NMNM030453 / POKER LAKE UNIT 82 30-015-27752-00-S1 NMNM0506A / POKER LAKE UNIT 83 / 30-015-27753-00-S1 STATE NMB10685 / POKER LAKE UNIT 84 / 30-015-29103-00-S1 NMLC061705B / POKER LAKE UNIT 85 / 30-015-27911-00-S1 NMLC061705B / POKER LAKE UNIT 86 / 30-015-27912-00-S1 NMLC061705B / POKER LAKE UNIT 87 / 30-015-27986-00-S1 NMLC061705B / POKER LAKE UNIT 89 / 30-015-27787-00-S1 NMNM030453 / POKER LAKE UNIT 92 / 30-015-27797-00-S1 NMNM030453 / POKER LAKE UNIT 93 / 30-015-27798-00-S1 NMNM030453 / POKER LAKE UNIT 93 / 30-015-27798-00-S1 NMNM030453 / POKER LAKE UNIT 99 / 30-015-32823-00-S1

Intermittent flaring was necessary due to restricted pipeline capacity at respective sales points.

4134 MCF was flared for the period Sept-Nov 2012