

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APR 29 2015
RECEIVED

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1512157315

OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. <i>AL0737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Poker Lake Unit 274 Tank Battery	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-35138	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	12	24S	29E	360	South	2310	East	Eddy

Latitude: N 32.225443° Longitude: W 103.936917°

NATURE OF RELEASE

Type of Release: crude oil and produced water	Volume of Release: 13 bbls oil and 9 bbls water	Volume Recovered: 3 bbls oil and 2 bbls water
Source of Release: water leg connection on the heater treater failed	Date and Hour of Occurrence: 4/20/15 @ 12:24 pm	Date and Hour of Discovery: 4/20/15 @ 12:24 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD, BLM via email	
By Whom? Bradley Blevins	Date and Hour: 4/21/15 @ 10:07 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* A connection on the water leg of the heater treater failed. The connection was repaired.		
Describe Area Affected and Cleanup Action Taken.* The release impacted approximately 3,700 sq. ft. of tank battery and well pad area including an area misted on the south side of the tank battery location. Vacuum truck recovered 5 bbls of fluid. The area will be remediated in accordance with the NMOCD and BLM remediation guidelines.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date: <i>5/1/15</i>	Expiration Date:
E-mail Address: bblevins@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: <i>4-24-15</i> Phone: 432-214-3704	REMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: *01/1/15*

ARP-2978