

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**  
ARTESIA DISTRICT  
Form C-141  
Revised August 8, 2011  
MAY 13 2015  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.  
**RECEIVED**

**Release Notification and Corrective Action**

*NAB1513450970*

**OPERATOR**  Initial Report  Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU Pierce Canyon 3 Fed. SWD #001, leak was in a poly line 300 ft. South of the Tank Battery location	Facility Type: SWD

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-40435
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	3	25S	30E					Eddy

Latitude N 32.15396° Longitude W 103.86378°

**NATURE OF RELEASE**

Type of Release: Crude oil	Volume of Release: 37 Bbls	Volume Recovered: 9 Bbls
Source of Release: 4" poly line	Date and Hour of Occurrence: 5/9/15, time unknown	Date and Hour of Discovery: 5/9/15 before noon.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, Jim Amos	
By Whom? Brad Blevins	Date and Hour: 5/9/15 at 6:11 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
An open ended poly line attached to the skim oil tank at the SWD was found leaking oil on the ground. The line was isolated and later removed.

Describe Area Affected and Cleanup Action Taken.\*  
The spill impacted approximately 2,755 sq.ft. of pasture area on a pipeline right of way south of the SWD. The free standing fluid was recovered with a vacuum truck. The stained area was left as pending the final remediation.  
The spill will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>5/14/15</i>	Expiration Date:
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>5/13/15</i> Phone: 432-556-8730	<b>Remediation per O.C.D. Rules &amp; Guidelines</b>	

\* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO**  
**LATER THAN: *6/15/15*** *2 RP 3000*