

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

MAY 29 2015 Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
ARTESIA DISTRICT with 19.15.29 NMAC.

Release Notification and Corrective Action

NABI515234386

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU-91 Flow line spill 1406 ft. south of the well at the JRU-29 SWD pad	Facility Type: Exploration and Production

Surface Owner: State of New Mexico	Mineral Owner: State of New Mexico	API No. 30-015-33601
------------------------------------	------------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	36	22S	30E					Eddy

Latitude N 32.346819° Longitude W 103.835167°

NATURE OF RELEASE

Type of Release: Crude oil and Produced water	Volume of Release: 1 bbl oil and 12 bbls PW	Volume Recovered: 3 bbls. PW
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence: 5/25/15 time unknown	Date and Hour of Discovery: 5/25/15 at approximately 2:00 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The flow line developed a leak due to external corrosion. A temporary repair clamp was placed on the leak, the lines will be replaced adjacent to the well pad and placed on cross ties.

Describe Area Affected and Cleanup Action Taken.*
The spill impacted approximately 300 sq.ft. of pasture area and approximately 750 sq.ft. of well pad-road area. This is the same general area as the reported spill at the JRU-29 Well pad on 12/25/14. Reference spill #2RP-2726.
The areas will be cleaned up in accordance to the NMOCD guidelines for spill remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>6/1/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: <i>5/29/15</i> Phone: 432-556-8730	SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: *6/1/15* *2RP-3023*

* Attach Additional Sheets If Necessary