(August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135

5. Lease Serial No. NMLC066087

SUNDAT NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

Do not use this form for proposals to drill or to re	onter on			
abandoned well. Use form 3160-3 (APD) for such proposals.		6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on rev	erse side.	7. If Unit or CA/Agreement, Name and/or No.		
Type of Well ☐ Gas Well ☐ Other	- :	8. Well Name and No. ZIRCON 12-7 B2JK FEDERAL COM 1H		
2. Name of Operator Contact: JACKIE LAT MEWBOURNE OIL COMPANY E-Mail: jlathan@mewbourne.com		9. API Well No. 30-015-42713		
3a. Address PO BOX 5270 HOBBS, NM 88241	(include area code) 3-5905	10. Field and Pool, or Exploratory BONE SPRING		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, and State		
Sec 12 T19S R29E NESW 2585FSL 2055FWL		EDDY COUNTY, NM		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE	NATURE OF NOTICE, RI	EPORT, OR OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION				
□ Notice of Intent □ Acidize □ Dee	pen Product	ion (Start/Resume)		
☐ Alter Casing ☐ Frac	ture Treat	ation Well Integrity		
	Construction Recomp	olete		
	and Abandon Tempor	arily Abandon Drining Operations		
☐ Convert to Injection ☐ Plug	Back Water D	Disposal		
 Describe Proposed or Completed Operation (clearly state all pertinent details, includ If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No. or following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notices shall be filed only after all determined that the site is ready for final inspection.) 11/05/14 TD 12 1/4" hole @ 1423'. Ran 1423' of 9 5/8" 36# J55 LT&C (35:65:4) w/additives. Mixed @ 12.5#/g w/2.21 yd. Tail w/200 sks 14.8#/g w/1.33 yd. Plug down @ 8:00 P.M. 11/05/14. Circ 105 sks o slips w/70k#. Tested csg spool pack-off to 1500#. At 9:30 AM 11/07/mins, held OK. Drilled out with 8 3/4" bit. Copy of chart & schematic attached. 	locations and measured and true ve If file with BLM/BIA. Required sub- e completion or recompletion in a requirements. including reclamation	ortical depths of all pertinent markers and zones. sequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed once n, have been completed, and the operator has		
Bond on file: NM1693 nationwide & NMB000919	728/5	MAY 1 8 2015		
accepted for record				
	MOCD	RECEIVED		
14. I hereby certify that the foregoing is true and correct. Electronic Submission #279917 verifie For MEWBOURNE OIL COM Committed to AFMSS for processing Name (Printed/Typed) JACKIE LATHAN		ACCEPTED FOR RECORD		
Signature (Electronic Submission)	Date 11/17/2014	MAY - 8 2015		
THIS SPACE FOR FEDERA	L OR STATE OFFICE U			
Approved By	Title	BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office			



PO Box 7 Lovington, NM 88260 (575) 224-2345 (575) 942-9472

ompany Date	in the second
ease Zracung 12NA IDSR Fed Con 119 Gounty 2 1/2/1/2	**************************************
Orilling Contractor Plug & Drill Pipe Size	e.P.
Accumulator Function Test - 00&G0#2	
b Check = USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)	
• Make sure all rams and annular are open and if applicable HCR is closed.	
Ensure accumulator is pumped up to working pressure! (Shut off all pumps)	
	No.
1. Open HCR Valve: (If applicable)	
2: Close annular.	A
3. Close all pipe rams.	r in
4: Open one set of the pipe rams to simulate closing the blind ram.	
5: For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems	ARES
6. Record remaining pressure 1.2.9.3. psi. Test Falls if pressure is lower than required.	7)4
a. (950 psi for a 1500 psi system) b. (1200 psi for a 2000 & 3000 psi system)	
7. If annular is closed, open it at this time and close HCR.	
7 II amuta is crosed, open to a tills tille and crose new.	

To Check : PRECHARGE ON BOTTLES OR SPHERICAL (III A 2.d.)

- Start-with manifold pressure at, or above, maximum acceptable pre-charge pressure:

 8. (800 psi for a 1500 psi system) b. (1100 psi for 2000 and 3000 psi system)
 - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
 - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to
 - 3. Record pressure drop psi. Test fails if pressure drops below minimum.
- Minimum: a: (700 psi for a 1500 psi system) b: (900 psi for a 2000 & 3000 psi system)

To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold
- Open the bleed off valve to the tank, (manifold psi should go to 0 psi) close bleed valve
 - 1. Open the HCR valve, (if applicable).
 - 2. Close annular
 - 3. With pumps only, time how long it takes to regain the required manifold pressure.
 - 4. Record elapsed time // SS . Test fails if it takes over 2 minutes.
- 6 a (950 psi for a 1500 psi system) b (1200 psi for a 2000 & 3000 psi system)



PO Box 7 Lovington, NM 88260 (575) 942-9472

Invoice B 4636

	State 10 10 County 10 20 1	
Lease Z VCCAA DA 7 BUSH	State (1 (1)) County (1) BOP: Annular:	COMPTENDED TO SECOND
Company Man	Casing:	
Drilling Contractor 山	Rig # 7/ S Pipe Phread Size 4/8 7/8 Pumps	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	Low Test High Test	
Test # Items tested	PSI Min PSI Min Remarks	
I Tamey Stest	Per Company Man Ran	is 4.
	BOSE BOSE BOY A FILL & KEIL & SIG	200 17 18 18 18 18 18 18 18 18 18 18 18 18 18
3 14 10 20 34 34 3		
U 7 / Table All Table		7
5 7 47 6 7 6 11 11		
6 7 1	Wind Childe	
8 1155		
	Du La Carlo Ca	2
10. 17		
W 18		
=12 -10	Land and a dear many	
and the second s		
	可est,accepted.by	
Mileage 4 () @/mile_=		
Methanol = = =		
Cup Test		
<u> </u>		
	ide <u>sus.</u>	
Subtotal =		
Tax = 75.		
TOTAL = LATOT		













