OCD Artesia

NM OIL CONSERVATION


UNITED STATES

FORM APPROVED OMB NO. 1004-0135

•	EPARTMENT OF THE IN UREAU OF LAND MANAG		ARTESIA	DISTRICT	Expires	: July 31, 2010	
SUNDRY NOTICES AND REPORTS ON WELLS JUN 1 2015 Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				1 2015	Lease Serial No. NMNM97113		
				6. If Indian, Allottee	or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agr NMNM117406		l/or No.	
1. Type of Well ☐ Oil Well ☑ Gas Well ☐ Other					8. Well Name and No HOT SEAT FED		
Name of Operator Contact: DAVID A EYLER COG OPERATING LLC E-Mail: DEYLER@MILAGRO-RES.CO					9. API Well No. 30-015-35776-	00-S2	
3a. Address ONE CONCHO CENTER 600 MIDLAND, TX 79701	O W ILLINOIS AVENUE	3b. Phone No Ph: 432-68	(include area code) 37-3033		10. Field and Pool, o CHOSA DRAV	r Exploratory /	
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)				11. County or Parish	and State	
Sec 35 T24S R25E NENE 990	OFNL 660FEL				EDDY COUNT	Y, NM	
12. СНЕСК АРРІ	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF N	IOTICE, RE	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	·		TYPE OF	ACTION		· .	
Notice of Intent ■	☐ Acidize	☐ Dee	pen	☐ Producti	on (Start/Resume)	☐ Water Sh	ut-Off
	☐ Alter Casing	☐ Frac	ture Treat	□ Reclama	ntion	☐ Well Integ	grity
☐ Subsequent Report	□ Casing Repair	□ Nev	Construction	☐ Recomplete		☐ Other	
☐ Final Abandonment Notice	☐ Final Abandonment Notice ☐ Change Plans ☐ Plug and Abandon ☐ Tempo		☐ Tempora	arily Abandon			
	☐ Convert to Injection	☐ Plug	Back	☐ Water D	isposal		
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for final form of the involved testing has been completed. Final At determined that the site is ready for final form of the involved testing has been completed. Final At determined that the site is ready for final final form of the involved final f	rk will be performed or provide the operations. If the operation result operations. If the operation result operation result operation. If the operation result operation. P-@-+/-7,895; DUMP-BAIL-PUMP-25-SXS:CMT-@-5,803'-5,463'(T/B.S.); WOC X00'-2,870'(SPACER PLUG 555'-1,374'(T/DLWR,9-5/8''C 1,195'(B/SALT); WOC RC.TO SURF., FILLING ALLHEAD 3' B.G.L.; WELD CWE PLAN TO USE THE COME PER OCD RULE 19.15.17	-4 SXS.CM-950'-5,800'. TAG CMT. CSG.SHOE X TAG CMT. CN TAG CMT.	n file with BLM/BIA e completion or recordequirements, including the completion of t	Required submpletion in a ning reclamation 3'. P87 1-498 MT. PLUG. 287'-3'. X INSTALI A STEEL T SEE A COND	Sequent reports shall be ew interval, a Form 31, have been completed by S.5.70 B.S. P.S. P.S. P.S. P.S. P.S. P.S. P.S.	Filed within 30 da 50-4 shall be filed and the operator he seem to be seen to	ays once nas
	Electronic Submission #29 For COG OP ommitted to AFMSS for proc	ERATING L	.C, sent to the Ca	rlsbad	•		
Manic (Trinical Typea) DAVID A	EILLIN ,		AUC AGENT		<u> </u>		
Signature (Electronic S	Submission)		Date 04/16/20)15			
	THIS SPACE FOR	RFEDERA	L OR STATE (OFFICE US	SE	•	
Approved By James	a. Comos		Title SF	ET		5-2 Date	18-15
onditions of approval, if any, are attached rifig that the applicant holds legal or equiple to condu	itable title to those rights in the si		Office 12	i P	•		

, i - 45 - 11 +65 4		
Author:	Stroup	
Well Name	Hot Seat Fed Well No	#2
Field	Chosa Draw API#	30-015-35776
County	Eddy Prop#	
State	New Mexico Zone	Morrow
Date	2/19/2013	
GL	3594:	
KB	3611	

Description	O.D.	Grade	Weight	Depth	Cmt Sx	TOC
Surface Csg	13 3/8	H40	48	237	300	Surface
Inter Csg	9 -5/8	J55	36	1,505	650	Surface
Prod Csg	5 1/2	P110	17	11,870	4,040	540
Liner						



Bullhead squeeze 5 1/2"-9 5/8" annulus w/1300sx

TOC @ 540'

17-1/2" Hole

13-3/8" (H40.-48#) @ 237: w/300 sx TOC @ surface

(162) ITS, Z-7/8" I-55 (12/31/14)

_ (203) 1" RODS TOC @ 1300'

51/2" x 2-7/8" DTA (RHS NO TURN TOOL)@ ??

12 1/4" hole

9-5/8" (J55 - 36#) @ 1505' w/650 sx

TOC @ surface

5956-6395 1st Bone Spring

6005'-6100' Bone Spring

6300'-6395' Bone Spring

6648-6756 2nd Bone Spring

CIBP @ 7895'

7930-8030 3Rd Bone Spring

Cmt 8320-8500

DV Tool @ 8516' w/1925' sx

Cmt 11000-11190 11124-11129

CIBP @ 11200' w/cmt

11214-11216: 11279-11282: 11292-11297

CIBP @ 11375' w/cmt

Morrow

11403 - 11436'

Cmt Retainer @ 11455 w/150 sx


11478-11490 & 11494-11497

8 3/4" hole.

5-1/2" (P110 - 17#) @ 11870" w/815 sx

Author:	Stroup	
10. 8K 9 % K 1 K 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Hot Seat Fec Well No.	#2
Field	Chosa Draw API #	30-015-35776
County	Eddy Prop#	, which is a second of the sec
State	New Mexico Zone:	Morrow
Date	2/19/2013	The standard of the standard o
GL	3594	
KB	3611	

Description	Ó D	Grade	Weight	Depth	Cmt Sx	тос
Surface Csg	13 3/8	H40	48	237	300	Surface
Inter Csg	9 +5/8	J55	36	1.505	650	Surface
Prod Csg	·5···1/2	P110∓	17.	11.870	4,040	540′
Liner						



Hole Size 17/2	
300 SXS Cement	
TOC At Surt	
133/2 Casing Set at 237	
Hole Size 121/4"	
650 SXS Cement	
TOC At Surf	
70C At Surf 95/8" Casing Set at 1505	·
Hole Size 7 1/2 SXS Cement	
TOC AT 1300	
jet stage 815 circ	
2 md stage 1925 3x Toc 1300 T/s	り
Renedial 1300 SF TOC 540 CBL	
51/2 Casing Set al 11870 TO At PETD	Mind Typeda

Operator COC	
Wall Name Mo. 1	
API 300153	
990 DIS 660 DI	
T24 S R 25 6	Eddy CTY
,	7
R-111-P	Hamiltonia de Maria Chillera
Secretary Potas	
Cave/Karst	-
LPC Habitat	
Top Solt Top Rent	300
	1250
	•
FORMATIONS	
Bell Cyn	1424
Cherry Cyn	2424.
Bushy Cyn	407.8
Bone Spring	5.22.8
X Wolf Camp	8414
same of the same services of t	10333
AtoKa	10 67 2
2 / M MC	11678
MR CL.	11275
55/10 L M.R	11544
CR 5974 SQZ 175	caper 305%
BSDVT 851L	-f-
BS Druman ZI.	•
PERFORATION 8500 -8	773.
which the state of	
11.15.1	1/2/4 dosod
some commence for the formation of the second	11129 MC
8030 \$2	7970 135
6754 5035	6605 BS
TOC 10701	Some Solar market was
MR	
11500 61860	
	•

James A. Amos 575-234-5909 575-361-2648

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

NM OIL CONSERVATION

ARTESIA DISTRICT

JUN 1 2015

RECEIVED

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

J. Amos 3/6/11



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office .620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310 .

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Solomon Hughes Natural Resource Specialist 575-234-5951

Jeffery Robertson Natural Resource Specialist 575-234-2230

Duncan Whitlock Environmental Protection Specialist 575-234-5926

Linda Denniston Environmental Protection Specialist 575-234-5974

Douglas Hoag Civil Engineering Tech 575-234-5979 Cody Layton Supervisory Multi Resources 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612