تا Form 3160-5								
(August 2007)		UNITED STATE	INTERIOR	OCD /	Irtesia	OMB NO	APPROVED O. 1004-0135 July 31, 2010	
	BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS			5. Lease Serial No. NMNM0506A				
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.						7. If Unit or CA/Agreement, Name and/or No. 891000303X		
1. Type of Well ☑ Oil Well □ Gas Well □ Other						8. Well Name and No. POKER LAKE UNIT 402H		
2. Name of Operator BOPCO LP Contact: WHITNEY MCKEE E-Mail: wbmckee@basspet.com						9. API Well No. 30-015-41229-00-X1		
3a. Address P O BOX 276 MIDLAND, T			3b. Phone No. (include Ph: 432-683-2277	area code)		10. Field and Pool, or POKER LAKE	Exploratory	
		R., M., or Survey Descriptio	n)			11. County or Parish, a	and State	
Sec 33 T24S	8 R31E SENE 1530	OFNL 930FEL				EDDY COUNTY	Υ, NM	
12	2. CHECK APPR	OPRIATE BOX(ES) T	O INDICATE NATU	RE OF N	OTICE, R	L EPORT, OR OTHE	R DATA	
TYPE OF SU	JBMISSION			TYPE OF	ACTION	·		
🔀 Notice of In	atent	☐ Acidize	🗖 Deepen		🗖 Produc	tion (Start/Resume)	□ Water Shut-Off	
—	,	□ Alter Casing	Fracture Tree		🖸 Reclam		Well Integrity	
 Subsequent Report Final Abandonment Notice 		Casing Repair	—			mplete Change to Orig		
					porarily Abandon PD r Disposal			
following compl	eletion of the involved o	perations. If the operation 1	y, give subsurface locations le the Bond No. on file with results in a multiple comple	BLM/BIA	. Required sumpletion in a	new interval, a Form 316	0-4 shall be filed once	
following compl testing has been determined that BOPCO, L.P. The change t string of 13-3 at 4,363?. Th KOP at 7,455 packer set 10	eletion of the involved of completed. Final Aba the site is ready for fin respectfully reque to the original APD 3/8? 54.50 lb/ft J-5? he intent is to run 7 5?. A 4-1/2? OHCS	perations. If the operation r ndonment Notices shall be f al inspection.) ests to amend the appr is due to severe losse 5 ST&C set at 916? an ? 26 lb/ft HCP-110 BT S will be ran through th asing, top of liner set a	te the Bond No. on file with results in a multiple comple filed only after all requirem roved 8 pt. for the PLL es in the Brushy Canyo d a string of 9-5/8? 40 C casing inside our 8- e curve and lateral with	a BLM/BIA tion or reco ents, includi #402H, A on. Currer Ib/ft J-55 3/4? open h a hange	. Required sumpletion in a ng reclamatic PI #30-015 ttly we have LT&C set hole dowr er and liner	new interval, a Form 316 n, have been completed; 5-41229. e a h to to	0-4 shall be filed once and the operator has	
following compl testing has been determined that BOPCO, L.P. The change t string of 13-3 at 4,363?. Th KOP at 7,455 packer set 10	eletion of the involved of completed. Final Aba the site is ready for fin respectfully reque to the original APD 3/8? 54.50 lb/ft J-55 he intent is to run 7 5?. A 4-1/2? OHCS 00? inside the 7? c	perations. If the operation r ndonment Notices shall be f al inspection.) ests to amend the appr is due to severe losse 5 ST&C set at 916? an ? 26 lb/ft HCP-110 BT S will be ran through th asing, top of liner set a	te the Bond No. on file with results in a multiple comple filed only after all requirem roved 8 pt. for the PLL es in the Brushy Canyo d a string of 9-5/8? 40 C casing inside our 8- e curve and lateral with	a BLM/BIA tion or reco ents, includi #402H, A on. Currer Ib/ft J-55 3/4? open h a hange	. Required sumpletion in a ng reclamatic PI #30-015 ttly we have LT&C set hole dowr er and liner	new interval, a Form 316 n, have been completed; 5-41229. e a n to top NM OIL CO ARTESI	0-4 shall be filed once and the operator has	
following compl testing has been determined that BOPCO, L.P. The change t string of 13-3 at 4,363?. Th KOP at 7,455 packer set 10	eletion of the involved of completed. Final Aba the site is ready for fin respectfully reque to the original APD 3/8? 54.50 lb/ft J-55 he intent is to run 7 5?. A 4-1/2? OHCS 00? inside the 7? c	perations. If the operation r ndonment Notices shall be f al inspection.) ests to amend the appr is due to severe losse 5 ST&C set at 916? an ? 26 lb/ft HCP-110 BT S will be ran through th asing, top of liner set a	te the Bond No. on file with results in a multiple comple filed only after all requirem roved 8 pt. for the PLL is in the Brushy Canyo d a string of 9-5/8? 40 C casing inside our 8- e curve and lateral with at 7,355?. The followin	BLM/BIA tion or reco ents, includi #402H, A on. Currer Ib/ft J-55 3/4? open h a hange g change	Required sumpletion in a ng reclamatic PI #30-015 PI #3	new interval, a Form 316 on, have been completed; 5-41229. e a n to top NM OIL CO ARTESIA	0-4 shall be filed once and the operator has NSERVATION A DISTRICT	
following compl testing has been determined that BOPCO, L.P. The change t string of 13-3 at 4,363?. Th KOP at 7,455 packer set 10 alter the appr	eletion of the involved of completed. Final Aba the site is ready for fin 7. respectfully reque to the original APD 3/8? 54.50 lb/ft J-55 he intent is to run 7 5?. A 4-1/2? OHCS 00? inside the 7? of roved directional p	perations. If the operation r ndonment Notices shall be f al inspection.) ests to amend the appr is due to severe losse 5 ST&C set at 916? an ? 26 lb/ft HCP-110 BT 5 will be ran through the asing, top of liner set a lan.	te the Bond No. on file with results in a multiple comple filed only after all requirem roved 8 pt. for the PLL is in the Brushy Canyo d a string of 9-5/8? 40 C casing inside our 8- e curve and lateral with at 7,355?. The followin #285988 verified by the BOPCO LP, sent to the	BLM/BIA tion or reco ents, includi #402H, A on. Currer Ib/ft J-55 3/4? open h a hange g change g change	Required sumpletion in a ng reclamatic PI #30-015 titly we have the set of the down of the down of a will not so will not the set of the down of the set of the down of the set of the down of the set	new interval, a Form 316 on, have been completed; 5-41229. e a n to top NM OIL CO ARTESIA SEP REC n System 15CQ0437SE)	NSERVATION A DISTRICT 0 3 2015	
following compl testing has been determined that BOPCO, L.P. The change t string of 13-3 at 4,363?: Th KOP at 7,455 packer set 10 alter the appr	eletion of the involved of completed. Final Aba the site is ready for fin P. respectfully reque to the original APD 3/8? 54.50 lb/ft J-57 ne intent is to run 7 5?. A 4-1/2? OHCS 00? inside the 7? of roved directional p	rue and correct. Electronic Submission For mitted to AFMSS for pr AUN	te the Bond No. on file with results in a multiple comple filed only after all requirem roved 8 pt. for the PLL es in the Brushy Canyo C casing inside our 8- e curve and lateral with at 7,355?. The followin #285988 verified by the BOPCO LP, sent to th rocessing by CATHY Q	BLM/BIA tion or reco ents, includi #402H, A on. Currer Ib/ft J-55 3/4? open h a hange g change g change	Required sumpletion in a ng reclamatic PI #30-015 titly we have the set of the down of the	new interval, a Form 316 on, have been completed; 5-41229. e a n to top NM OIL CO ARTESIA SEP REC n System 15CQ0437SE)	NSERVATION A DISTRICT 0 3 2015	
following compl testing has been determined that BOPCO, L.P. The change t string of 13-3 at 4,363?. Th KOP at 7,455 packer set 10 alter the appr 14. Thereby certify Name (<i>Printed/T</i>	eletion of the involved of completed. Final Aba the site is ready for fin respectfully reque to the original APD 3/8? 54.50 lb/ft J-5? he intent is to run 7 5?, A 4-1/2? OHCS 00? inside the 7? of roved directional p y that the foregoing is t Con Typed) BRIAN BR/	perations. If the operation r ndonment Notices shall be f al inspection.) ests to amend the appr is due to severe losse 5 ST&C set at 916? an ? 26 lb/ft HCP-110 BT S will be ran through the asing, top of liner set a lan. rue and correct. Electronic Submission For mitted to AFMSS for pr AUN	te the Bond No. on file with results in a multiple comple filed only after all requirem roved 8 pt. for the PLL rs in the Brushy Canyo d a string of 9-5/8? 40 C casing inside our 8- e curve and lateral with at 7,355?. The followin ACCE W W W W W W W W W W	BLM/BIA tion or reco ents, includi #402H, A on. Currer Ib/ft J-55 3/4? open h a hange g change ptect for NMCC BLM Wel e Carlsbae UEEN on C DRILLIN	Required sumpletion in a ng reclamatic PI #30-015 titly we have the second sec	new interval, a Form 316 on, have been completed; 5-41229. e a n to top NM OIL CO ARTESIA SEP REC n System 15CQ0437SE)	INSERVATION A DISTRICT 0 3 2015 CEIVED	
following compl testing has been determined that BOPCO, L.P. The change t string of 13-3 at 4,363?. Th KOP at 7,455 packer set 10 alter the appr 14. Thereby certify Name (Printed/T	eletion of the involved of completed. Final Aba the site is ready for fin respectfully reque to the original APD 3/8? 54.50 lb/ft J-5? he intent is to run 7 5?, A 4-1/2? OHCS 00? inside the 7? of roved directional p y that the foregoing is t Con Typed) BRIAN BR/	perations. If the operation in indomment Notices shall be f al inspection.) ests to amend the appr is due to severe losse 5 ST&C set at 916? an ? 26 lb/ft HCP-110 BT 5 will be ran through the asing, top of liner set a lan. rue and correct. Electronic Submission For mitted to AFMSS for pr AUN bmission) THIS SPACE F	te the Bond No. on file with results in a multiple comple filed only after all requirem roved 8 pt. for the PLL es in the Brushy Canyo d a string of 9-5/8? 40 C casing inside our 8- e curve and lateral with at 7,355?. The followin #285988 verified by the BOPCO LP, sent to the rocessing by CATHY Q Title Date	BLM/BIA tion or reco ents, includi #402H, A on. Currer Ib/ft J-55 3/4? open h a hange g change g change BLM Wel e Carlsbac UEEN on C DRILLIN 12/22/20	Required sumpletion in a ng reclamatic PI #30-015 titly we have the second seco	new interval, a Form 316 on, have been completed; 5-41229. e a n to top NM OIL CO ARTESI SEP REC n System 15CQ0437SE) EER	NSERVATION A DISTRICT 0 3 2015 CEIVED	
following completesting has been determined that BOPCO, L.P. The change t string of 13-3 at 4,363?. The KOP at 7,455 packer set 10 alter the approximation of the string of 13-3 at 4,363?. The KOP at 7,455 packer set 10 alter the approximation of the string of 13-3 at 4,363?. The string of 13-3 at 4,363? T	eletion of the involved of completed. Final Aba the site is ready for fin Prespectfully reque to the original APD 3/8? 54.50 lb/ft J-53 be intent is to run 7 5?. A 4-1/2? OHCS 00? inside the 7? of roved directional p (Electronic Su Con Typed) BRIAN BR/ (Electronic Su Charles N cal, if any, are attached. cant holds legal or equi the applicant to conduc	perations. If the operation r ndonment Notices shall be f al inspection.) ests to amend the appr is due to severe losse 5 ST&C set at 916? an ? 26 lb/ft HCP-110 BT 3 will be ran through the asing, top of liner set a lan. rue and correct. Electronic Submission For mitted to AFMSS for pr AUN THIS SPACE F JIMMER	te the Bond No. on file with results in a multiple comple filed only after all requirem roved 8 pt. for the PLL es in the Brushy Canyo d a string of 9-5/8? 40 C casing inside our 8- e curve and lateral with at 7,355?. The followin #285988 verified by the BOPCO LP, sent to the rocessing by CATHY Q Title Date COR FEDERAL OR PEROLI Title con warrant or he subject lease Office	A BLM/BIA tion or reco ents, includi #402H, A on. Currer Ib/ft J-55 3/4? open h a hange g change change BLM Wel e Carlsbae UEEN on C DRILLIN 12/22/20 STATE C	Required sumpletion in a ng reclamatic pl #30-015 tilly we have the second seco	new interval, a Form 316 on, have been completed; 5-41229. e a n to top NM OIL CO ARTESI SEP REC n System 15CQ0437SE) EER AUG 2	INSERVATION A DISTRICT 0 3 2015 CEIVED OR RECORD 8 2015	

.

BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED

•

BOPCO, L.P. respectfully requests to amend the approved 8 pt. for the PLU#402H, API #30-015-41229. The change to the original APD is due to severe losses in the Brushy Canyon. Currently we have a string of 13-3/8" 54.50 lb/ft J-55 ST&C set at 916' and a string of 9-5/8" 40 lb/ft J-55 LT&C set at 4,363'. The intent is to run 7" 26 lb/ft HCP-110 BTC casing inside our 8-3/4" open hole down to KOP at 7,455'. A 4-1/2" OHCS will be ran through the curve and lateral with a hanger and liner top packer set 100' inside the 7" casing, top of liner set at 7,355'. The following changes will not alter the approved directional plan.

2nd intermediate string of casing:

- 7" 26 lb/ft HCP-110 BTC casing
 - o Collapse: 7,800 Psi
 - o Set Depth: 7,455'
- Cement volumes:
 - o 1st stage lead: 250 sacks of Class H cement
 - Density: 12.5 ppg
 - Yield: 1.89 ft³/sack
 - H₂O requirement: 10.52 gal/sack
 - 1st stage tail: 200 sacks of Class H cement
 - Density: 13.0 ppg
 - Vield: 1.68 ft³/sack
 - $H_2O: 9.01 \text{ gal/sack}$
 - o 2nd stage lead: 190 sacks of Class C
 - Density: 13.5 ppg
 - Yield: 1.72 ft³/sack
 - H₂0: 9.12 gal/sack
 - TOC approx. 1,000' overlap into 9-5/8" casing

Production Casing: (OHCS)

- 4-1/2" 11.6 lb/ft HCP-110 BTC casing
 - Liner top set @ 7,355'
 - Collapse: 8,650 psi
 - Set Depth: 16,541'