Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103 May 27, 2004
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-015-20550 5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa re, INIVI 87303	6. State Oil & Gas Lease No. B-2130
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLI	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name ETZ State Unit
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other Injection RECEIVE	8. Well Number 103
2. Name of Operator Mack Ene	gy Corporation JUL 2 7 2005	9. OGRID Number 013837
3. Address of Operator	900-MATE	10. Pool name or Wildcat
4. Well Location	0 Artesia, NM 88211-0960	Grbg Jackson SR Q Grgb SA
	660feet from theNorth line and	1980 feet from the West line
Section 16	Township 17S Range 30B	NMPM County Eddy
	11. Elevation (Show whether DR, RKB, RT, GR, 3685' GR	etc.)
Pit or Below-grade Tank Application ☐ Pit type Depth to Groundy	or Closure [_] vater Distance from nearest fresh water well	Distance from negrest surface water
Pit Liner Thickness: mil		Construction Material
12. Check	Appropriate Box to Indicate Nature of Noti	ce, Report or Other Data
		UBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL W	ORK ALTERING CASING
TEMPORARILY ABANDON PULL OR ALTER CASING		DRILLING OPNS.□ P AND A ⊠ IENT JOB □
OTHER:	☐ OTHER:	
13. Describe proposed or comp	oleted operations. (Clearly state all pertinent details ork). SEE RULE 1103. For Multiple Completions:	, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
7/18/05 Set 4-1/2" CIBP @ 2433',	cap w/ 35' cmt. w/ bailer.	
7/18/05 Circ hole w/ MLF.	•	
7/18/05 Perf 4-holes @ 1100', set p 7/19/05 Tag plug @ 940'.	kr. @ //5', sqz. 40 sx. cmt.	
7/19/05 Perf 4-holes @ 601', set pk 7/19/05 Perf 4-holes @ 60', pump 3	r. @ 250', sqz. 40 sx. cmt., tag plug @ 428'. 0 sx. cmt. down 4-1/2" to surf out of 8-5/8", leave	
7/20/03 RDMO. Cut off wellnead &	anchors, install dry hole marker, and clean location	1.
		JUL 2 6 2005
I hereby certify that the information grade tank has been/will be constructed or	above is true and complete to the best of my knowl closed according to NMOCD guidelines , a general permi	edge and belief. I further certify that any pit or below- t or an (attached) alternative OCD-approved plan .
SIGNATURE TO M	TITLEAgent_	DATE7/21/05_
Type or print name Roger Mas	ssey ———————————————————————————————————	Telephone No. (432) 530-0907
For State Use Only	/ 00	NOV 1 a some
APPROVED BY:	TITLE Field St	pervisor NOV 10 Z003



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL	RICHARDSON
	Governor

Joanna Prukop Cabinet Secretary Acting Director

Oil Conservation Division

RECEIVED

OCT 3 1 7005

OCUMENTEDIN

27 July 2005

Mack Energy Corp. P. O. Box 960

Artesia, New Mexico 88221-0960

Form C-103 Report of Plugging for your ETA State Unit # 103 C-16-17-30 API 30-015-20550 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- 1. All pits have been closed as per Rule 50.
- 2. Rat hole and cellar have been filled and leveled.
- 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- 5. The dead men and tie downs have been cut and removed.
- 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Jeny W. Shendl Production Clerk 10-31-2005

Van Barton Field Rep. II