Form 3160-5

UNITED STATES

OCD-ARTESIA

FORM APROVED

. 3	ARTMENT OF THE INTERIOR	TMENT OF THE INTERIOR J OF LAND MANAGEMENT ICES AND REPORTS ON WELLS		OMB NO. 1004-0135	
				EXPIRES: NOVEMBER 30, 2000 15. Lease Serial No.	
			NMLC064050A		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals				6. If Indian, Allottee or Tribe Name	
	SUBMIT IN TRIPLICATE				
				7. Unit or CA Agreement Name and No.	
1a. Type of Well Oil Well Gas Well Other					
				8 Well Name and No.	
2. Name of Operator DEVON ENERGY PRODUCTION COMPANY, LP				9. API Well No.	34 C Federal 51
3. Address and Telephone No.					-015-33272
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-8198				10. Field and Pool, or Exploratory	
4. Location of Well (Report location clearly and in accordance with Federal requirements)*				Red Lake Glorieta-Yeso, NE	
990 FNL 1650 FWL				12. County or Parish 13. State	
SEC 34 T17S R27E, UNIT C				Eddy NM	
	CK APPROPRIATE BOX(s) TO INDIC	CATE NATURE OF NOT	ICE REPORT	<u>-</u>	
TYPE OS SUBMISSION	TAT TO MALE BOX(3) TO MORE		E OF ACTION	,	
[/] Nation of Texast	Acidize [Deepen	Productio	n (Start/Resume)	☐ Water Shut-Off
✓ Notice of Intent	Alter Casing	Fracture Treat	Reclamati	ion	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomple		☐ Other
Final Abandonment Notice	☐ Change Plans☐ Convert to Injection☐	☐ Plug and Abandon ☐ Plug Back	☐ Water Dis	rarily Abandon	
Devon Energy Production Company 1. MIRU PU. TOH with rods ar 2. Pick up RBP and RIH on tul 3. PU bailer and RIH on tubing 4. MIRU pump truck. Pressure 5. RIH with 3-1/8" casing gun a wireline, RDMO same.	nd pump. ND tree, NU BOP. T bing. Set RBP at +1- 2850'. T g. Dump 10 sand on top of RB test RBP and casing to 4000	TOH with tubing. TOH with tubing. P. TOH with tubing psi.	800'-2500'.	TOH with	
6. MIRU BJ. Acidize & frac San Andres perfs.				IPPROVE	
7. Open well up and flow back frac load until well dies.					
9. RIH with SN, with nothing below it. Set SN +/-15' below bottom perf. 10. RIH with pump and rods. Hang well on and put well to test to battery.					
10. RIH with pump and rods. Hang well on and put well to test to battery. ORIG. SGD.) ALEXISCOMA					
) A PE	LEXIS C. SWOBC TROLEUM ENGIN	IEER
				111022.011	
14. Thereby certify that the foregoing	is true and correct				
Signed \(\text{Signed} \)	Name _	Norvella Ada Sr. Staff Engineering		Date	12/30/2005
(This space for Federal or State Office	use)				
Approved by	,			Data	
Conditions of approval, if any:	Title			Date	

*See Instruction on Reverse Side

The To U.S.C. Section Tool, makes it a Uniter of any person knowingly and willough make any department of agency of the Onlined States any raise, includes or maddoment statements of representations to any matter which

RECEIVED JAN 1 3 2006 OCU-ARTESIA