Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			5. Lease Serial No. NM-18214 6. If Indian, Allottee or Tribe Name	
1. Type of Well Oil Well A Gas Well Ott	her	8. Well Name and	i No.	
			eral #1	
2. Name of Operator Yates Petroleum Corporation			51 d1 # 1	
3a. Address 3b. Phone No. (include area code		9. API Well No. 30-005-0015	30-005-00159	
105 S. 4th Str., Artesia, NM 88210	505-748-1471	505-748-1471 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)		Rock Schoo	lhouse Wolfcamp	
		11. County or Par	11. County or Parish, State	
660'FNL & 1980'FWL of Section 21-T8S-R26E (Unit C, NENW)			inty, New Mexico	
12. CHECK APPROPRIATE BOX(ES) T	O INDICATE NATURE O	F NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION	ION TYPE OF ACTION			
Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
X Notice of Intent Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Casing Repair	New Construction			
Subsequent Report	[]	Recomplete	Other	
Change Plans	Plug and Abandon	Temporarily Abandon		
Final Abandonment Notice Convert to Inject	ction Plug Back	Water Disposal		
following completion of the involved operations. If the operation results in testing has been completed. Final Abandonment Notices shall be filed of determined that the site is ready for final inspection.) Yates Petroleum Corporation plans to recomplet tubing and casing w/+/-15 bbls of 2% KCl treate 2-3/8" tubing fish cut at 4418' then RU a reverse over the tubing, the tubing anchor and the rest of clean and POOH with the work string and the war and the rest of the fish then circulate the hole clean the cement and the 1st CIBP at 4600' and the 5170' then push the plugs down to another CIBF clean POOH with the tubing. Perforate Cisco 56 (32). Set RBP at 5450'+/ Stimulate as needed productive.	te this well as follows: MII d water. POOH with the 2 e unit and circulate hole wing from the tubing down to the bash over pipe. RIH with nean then POOH with the fire cement and the 2nd CIE at 5920'+/- then circulate 670'-5678' (32). Stimulate	RU an safety equipment as 2-3/8" tubing and SN. RIH to the 2% KCl water (if needed ottom of the fish at 4544' the ecessary fishing tools to reposhing tools. RIH to the PB at 5030' and the cement as needed. Perforate Wol	needed. Load the o the top of the use air unit) & wash en circulate the hole move the 2-3/8" tubing TD of 4556' and drill and the 3rd CIBP at r. After the hole is fcamp 5382'-5390'	
14. I hereby certify that the foregoing is true and correct				
Name <i>(Printed/Typed)</i> Tina Huerta	Title Reau	latory Compliance Supervis	sor	
1	Time regu	omphanoc Oupervis	· · ·	
Signature (Juna Junta)	Date Febru	uary 12, 2006		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by (ORIG. SGD.) ALEXIS C. SWOBODA PRITROLEUM ENGINEEH Date FEB 2 2 2006				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willbully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction