

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1528841728

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production	Contact	Garry Michael, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575-513-4895
Facility Name	Ross Ranch 10 Fed 1 SWD	Facility Type	SWD

Surface Owner	Federal	Mineral Owner	Federal	API No.	30-015-29605
---------------	---------	---------------	---------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	10	26S	31E	1980	North	660	East	Eddy

Latitude: 32.059235486

Longitude: -103.75905787

NATURE OF RELEASE

Type of Release	Produced Water Spill	Volume of Release	400bbls	Volume Recovered	400bbls
Source of Release	Nipple on gun barrel	Date and Hour of Occurrence	October 1, 2015 6:34 PM	Date and Hour of Discovery	October 1, 2015 6:34 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos, BLM Kellie Jones, OCD		
By Whom?	David Washington, Assistant Production Foreman	Date and Hour	Jim Amos, BLM October 1, 2015 12:00 AM Kellie Jones, OCD October 1, 2015 12:05 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

NM OIL CONSERVATION
ARTESIA DISTRICT
OCT 15 2015
RECEIVED

If a Watercourse was Impacted, Describe Fully.*
N/A


Describe Cause of Problem and Remedial Action Taken.*

On October 1, 2015 6:34 PM at the Ross Ranch 10 Fed 1 SWD a 3" threaded nipple corroded on the gun barrel and caused a release of 400bbl produced water into lined containment. The Lease Operator immediately shut in the wells going to the SWD and did a lock out tag out on the gun barrel until repairs could be made.

Describe Area Affected and Cleanup Action Taken.*

All 400bbl of fluid released were contained in lined containment and a vac truck was called to clean up containment. All 400bbls produced water were recovered and the containment was checked for holes with none found.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher	OIL CONSERVATION DIVISION		
Printed Name: Sheila Fisher	Approved by Environmental Specialist: 		
Title: Field Admin Support	Approval Date: 10/15/15	Expiration Date:	
E-mail Address: Sheila.Fisher@dvn.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>	
Date: 10/13/2015 Phone: 575.748.1829			

* Attach Additional Sheets If Necessary

2RD-3337