

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1532733082

OPERATOR Initial Report Final Report

Name of Company Devon Energy Production <i>LO137</i>	Contact Mike McMahan Production Assistant Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.706.4165
Facility Name Burton Flat Deep Unit 38	Facility Type Oil

Surface Owner Federal	Mineral Owner State	API No. 30-015-25189
-----------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	2	21S	27E	467	FSL	467	FEL	EDDY

Latitude: 32.5030666 Longitude: -104.1527476

NATURE OF RELEASE

Type of Release Spill Oil & Produced Water	Volume of Release 5 BBL Oil & 5 BBL Produced water	Volume Recovered 3 BBL Oil & 0 BBL Produced Water
Source of Release Heater Treater	Date and Hour of Occurrence 11/16/15 at 4:30 PM	Date and Hour of Discovery 11/16/15 at 4:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD left message BLM left message	
By Whom? Mike McMahan	Date and Hour OCD 11/16/15 AT 5:00 pm BLM 11/16/15 AT 5:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

NM OIL CONSERVATION
ARTESIA DISTRICT
NOV 20 2015
RECEIVED

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

A pin hole leak on the 2 inch collar of drain line, the leak was on weld seam off collar. Opened drain line to divert fluid to open top tank and called for a vacuum truck.

Describe Area Affected and Cleanup Action Taken.*

5 BBL oil & 5 BBL of produced water was released on a 25X 3 area all on pad, 3 BBL of oil & 0 BBL of produced water was recovered. An environmental agency will be called out for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>11/23/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: Jeanette.barron@dvn.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 11/20/15 Phone: 575.748.1813	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *12/23/15*

2RP-3411