

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

DEC 31 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1400554655		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Oxy Permian Ltd.		Contact Casey Summers			
Address 6 Desta Drive, Midland, TX 79705		Telephone No. (575) 513-8289			
Facility Name McKittrick Hills Central Tank Battery		Facility Type Battery			
Surface Owner BLM		Mineral Owner		API No. 30-015-21010	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	14	22S	24E					Eddy County, NM

Latitude N 32.39755° Longitude W 104.46109°

NATURE OF RELEASE

Type of Release Oil and Produced water	Volume of Release 20 bbls oil, 160 bbls produced water	Volume Recovered 160 bbls
Source of Release Lack of alarms to warn of a tank overflow	Date and Hour of Occurrence 12/09/2015	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-NMOCD; Shelly Tucker-BLM	
By Whom? Cliff Brunson @ BBC International	Date and Hour 12/10/2015 @ 5:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Lack of alarms caused a tank to overflow spilling 20 bbls of oil and 160 bbls of produced water onto the ground. A vacuum truck recovered 160 bbls of fluids and the alarm issue was corrected.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 75' x 50' on location. Remediation will be completed in accordance with a remediation plan approved by both NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Casey Summers		Approved by Environmental Specialist: 	
Title: NM Environmental Advisor		Approval Date: 11/5/16	Expiration Date: N/A
E-mail Address: Casey.Summers@oxy.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 12/30/15 Phone: (575) 513-8289		SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 1/18/16	

* Attach Additional Sheets If Necessary

2RP-3471