
Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103
District I = (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II = (575) 748-1283		WELL API NO. 30- 015 - 30339
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> = (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		2029-61
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ATION FOR PERMIT" (FORM C-101) FOR SUCH	Oxy Duchess State
PROPOSALS.)		l
	Gas Well 🗹 Other	8. Well Number
2. Name of Operator	Marrie ( A.D. A.)	9. OGRID Number
3. Address of Operator	WTP Limited Partnership	192463 10. Pool name or Wildeat
	250 Midland, TX 79710	Logan Draw Morrow
4. Well Location		Con an wew rorrow
	1980 feet from the North line and	980 feet from the west line
	Township (75 Range 27E	<del></del>
Section 14	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	3451	
لىچىغ ئىمخەرىكى ئەگەرىكى سادادىرىقىدە كاھەدىكىلىدىنىنىلىدىن ھىندىدىنىدىكىلىسىمىللار		Same and the second of the sec
12. Check A	ppropriate Box to Indicate Nature of Notice,	, Report or Other Data
NOTICE OF IN	TENTION TO: SUE	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON P REMEDIAL WOR	
TEMPORARILY ABANDON		IILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL  CASING/CEMEN	IT JOB 🔲
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM   OTHER:	∏ OTHER:	г
	eted operations. (Clearly state all pertinent details, ar	nd give pertinent dates, including estimated date
	k). SEE RULE 19.15.7.14.NMAC. For Multiple Co	
proposed completion or reco		
ו	TD-9572' PBTD-9521' Perfs-9276-9314'	Approved for plugging of wall bore only.
	8-5/8" 32# csg @ 1492' w/ 940sx, 12-1/4" hole, TOC-	Surf-Circ Liability under bond is retained pending received
1	4-1/2" 11.6# csg @ 9572' w/ 675sx, 7-7/8" hole, TOC-	6570'-CBL of C-103 (Subsequent Report of Well Plugging
	L. RIH & set CIBP @ 9226', M&P 25sx cmt to 8975' 2. M&P 25sx cmt @ 8690-8440' WOC-Tag	which may be found at OCD Web Page under Forms, www.cmmrd.state.nm.us/oed.
	3. M&P 25sx cmt @ 8070-7820' WOC-Tag	
	1. Perf @ 6250', sqz 35sx cmt to 6150' WOC-Tag	NM OIL CONSERVATION
	5. Perf @ 5075', sqz 35sx cmt to 4975' WOC-Tag	ARTESIA DISTRICT
	5. Perf @ 3050', sqz 35sx cmt to 2950' WOC-Tag 7. Perf @ 1542', sqz 35sx cmt to 1442' WOC-Tag	DEC <b>3 0</b> 2015
	3. Perf @ 250' sqz 85sx cmt to surface	
	10# MLF between plugs	RECEIVED
	Above ground steel tanks will be utilized	
Spud Date:	Rig Release Date:	
wall BED wat ha	0/2021 hu 1-4-2017	<del></del>
· <del></del>	Plugged by 1-4-207	
I hereby certify that the information at	bove is true and complete to the best of my knowleds	ge and belief.
		<b>.</b> .
SIGNATURE	TITLE Sr. Regulatory Advise	DATE 12/21/15
•	· · · · · · · · · · · · · · · · · · ·	. (
Type or print nameDavid Stewart	E-mail address: <u>david_stewart</u>	@oxy.com PHONE: 432-685-5717
For State Hea Only	_	
For State Use Only	1 - PS	1./
APPROVED BY: // COU	TITLE DIST PLOPEW	1507 DATE 1/4/2016
Conditions of Approval (if any):	111. 1 12001	
N See	Attached COA's	

OXY USA WTP LP - Proposed OXY Duchess State #1 API No. 30-015-30339

85sx @ 250'-Surface 12-1/4" hole @ 1492' Perf @ 250' 8-5/8" csg @ 1492' w/ 940sx-TOC-Surf-Circ 35sx @ 1542-1442' WOC-Tag Perf @ 1542' 35sx @ 3050-2950' WOC-Tag Perf @ 3050' 35sx @ 5075-4975' WOC-Tag Perf @ 5075' 35sx @ 6250-6150' WOC-Tag Perf @ 6250' 25sx @ 8070-7820' WOC-Tag 25sx @ 8690-8440' WOC-Tag 7-7/8" hole @ 9572' 4-1/2" csg @ 9572' w/ 675sx-TOC-6570'-CBL CIBP @ 9226' w/ 25sx to 8975' Perfs @ 9276-9314' PB-9521

TD-9572'

PB-9521'



## NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

## CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: <u>OXY USA</u>
Well Name & Number: <u>Oxy Duchass Sketa /</u>
API #: 30 - 0/5 - 3039

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.
- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.
- 12. 19.15.7.16: B. In the case of a dry hole, a complete record of the well on form C-105 with the attachments listed in Subsection A of 19.15.7.16 NMAC shall accompany the notice of intention to plug the well, unless previously filed. The division shall not approve the plugging report or release the bond the operator has complied with 19.15.7.16 NMAC.

DATE: 1/4/2016

APPROVED BY (SU)

## N.M.O.C.D.- Guidelines For Plugging

- All cement plugs will be a minimum of 100' in length, or a minimum of 25sx. Of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sx. Of gel per 100 bbls. Of water.
- A cement plug is required to be set 50' below, and 50' above all casing shoes, and casing stubs. These plugs must be tagged.
- A CIBP with 35' of cement on top, may be set instead of 100' plug.
- A plug as indicated above, must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set above and below all salt zones, must be tagged.
- No more than 2000' is to be allowed between plugs in open hole, and no more than 3000' between plugs in cased hole.
- D.V. tools are required to have a 100' cement plug set 50' above, and 50' below the tool. **This** plug must be tagged.

Formations to be isolated with plugs placed at the top of each formation are:

- Fusselman
- Devonian
- Morrow
- Wolfcamp
- Bone Springs
- Delaware
- Any salt section (plug at top and bottom)
- Abo
- Glorietta
- Yates (this plug is usually at base of salt section)

If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths, or casing must be perforated and squeezed behind casing at the formation depths.

In the R-111P area (Potash mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated, and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible.