

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JAN 20 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1602127288

6/37

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production Company	Contact	Rudy Zuniga Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-390-5435
Facility Name	Hackberry 19 Fed 1	Facility Type	oil

Surface Owner	Federal	Mineral Owner	Federal	API No	30-015-30092
---------------	---------	---------------	---------	--------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	19	19S	31E	1980	North	1980	West	Eddy

Latitude: N 32°64'73.01"

Longitude: W 103°91'00.24"

NATURE OF RELEASE

Type of Release Spill	Oil	Volume of Release	65 bbls oil	Volume Recovered	60 bbls oil
Source of Release	Hole in bottom of tank	Date and Hour of Occurrence	1.19.16 @ 1:15 pm	Date and Hour of Discovery	1.19.16 @ 1:15 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Dara Glass @ BLM Heather Patterson @ OCD		
By Whom?	Jesse Armendariz Assistant Production Foreman	Date and Hour	1.19.16 @ 3:30 pm 1.19.16 @ 3:40 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.
N/A


Describe Cause of Problem and Remedial Action Taken.*

Two oil tanks had holes due to corrosion on bottom causing a 65 bbls oil release. Vac truck was called to transfer 60 bbls oil to third oil tank to prevent further release. Tanks will be repaired when possible.

Describe Area Affected and Cleanup Action Taken.*

65 bbls oil was released on the East side of the facility. 60 bbls oil were recovered via vacuum truck. All fluid remained on the pad inside unlined containment. Environmental Agency will be called for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Corina Moya	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 1/21/16	Expiration Date: N/A
E-mail Address: corina.moya@dvn.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 2/22/16	
Date: 1.20.2016 Phone: 575.746.5559		

* Attach Additional Sheets If Necessary

2RP-3504