Form 3160-5 (August 2007)

NMOCD

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

	Expires:	July
5.	Lease Serial No.	

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. FEE
6. If Indian, Allottee or Tribe Name

asanaona wam age form of our of Art Dy for such proposale.					•		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No. SCR384		
Type of Well	8. Well Name and No.						
Oil Well Gas Well O	GRYNBERG 35 COM 1						
Name of Operator GRYNBERG JACK J	TI	9. API Well No. 30-005-61174-00-S1					
3a. Address 3600 S. YOSEMITE SUITE 9 DENVER, CO 80237	. (include area code 0-7490	;)	10. Field and Pool, or Exploratory PECOS SLOPE-ABO				
4. Location of Well (Footage, Sec., 1	T., R., M., or Survey Description)				11. County or Parisl	, and State	
Sec 35 T5S R24E SENW 198	30FNL 1980FWL		٠.	• '	CHAVES COL	JNTY, NM	
12. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF	NOTICE, R	EPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION						
	☐ Acidize	☐ Deep	oen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off	
Notice of Intent ■	☐ Alter Casing		ture Treat	☐ Reclam	ation	■ Well Integrity	
☐ Subsequent Report	Casing Repair	_ □ New	Construction	— Recom		Other	
☐ Final Abandonment Notice	Change Plans	☐ Plug	and Abandon	☐ Tempor	arily Abandon		
	Convert to Injection	☐ Plug		□ Water I	Disposal		
testing has been completed. Final A determined that the site is ready for I Jack J. Grynberg and Associa attached procedure. Also included is the proposed	final inspection.) ates request permission to r			•		OIL CONSERVATION	
NOTE: This sundry replaces	doc. #00852-8742 as the p	rocedure,an	d WBD have be	en revised.	ne tred	FEB 2 9 2016	
Accepted for reconnection (U) 3/1	ord 2016		ACCEPTED FO		ONTH PERIOD 2 4 2016	RECEIVED	
14. I hereby certify that the foregoing f	Electronic Submission #33	BERG JACK	J, sent to the Re	oswell	-		
Name (Printed/Typed) JOE MA	•			LATORY MA			
						· · · · · · · · · · · · · · · · · · ·	
Signature (Electronic	Submission)		Date 02/22/2	2016			
ACCEPTED FOR	RECURD PACE FOR	R FEDERA	L OR STATE	OFFICE U	SE		
/S/ DAVID F	R. GLASS				,		
Approved By - FEB-2 4 26	H6		Title			Date	
Conditions of approval, if any, are attache tertify that the applicant holds legal or equivalent would entitle the Applicant of Gold	ed. Approval of this notice does notice does notice title to those rights in the s	ot warrant or ubject lease	Office				
Title 18 U.S.C. (13 ATTOR (1) O 1 To hid (1) 11 E 43	GPAF Seption 1212, make it a cr	rime for any pe	rson knowingly an	d willfully to m	ake to any department	or agency of the United	
States any false, fictitious or fraudulent	statements or representations as to	any matter wi	thin i				

** BLM REVISED ** BLM REVISED ** BLM REVIS

Accepted For Record By BLM For 3 Month Period Ending 05-24-2016. This Is Subject To Approval By The NMOCD. Contact The BLM Roswell Field Office During Office Hours Or After Office Hours At (575) 627-0205 At Least 24 Hours Prior To The Scheduled Casing Integrity Test.

Grynberg 35 Com #1

Proposed Re Completion Schematic 2/15/2016 in RED

TOC 167


1980 FNL 1980 FWL Section 35, TSS - R24E

Chaves County, NM API 30-05-61174

KB: 3932' GL: 3916'

Spud Date: 1/16/1982





2 3/8 Prod Tbg at top of perfs.

7 7/8" Hole 4 1/2" Casing Set @ 4107', Cemented with 1450 sx of 50/50 Poz

2nd proposed Perfs if lower zones not productive Perf @, 3470-3466, 3346-3326, 3379-3354, 3400-3385, 3407-3405.

2nd proposed CIBP @ 3550' if lower zones not productive

Proposed Perfs: 3639-3652, 3717-3718, 3742-3732

Set CIBP at 3755'

Perfs existing, 3769-3795, 3805-3816 3920-3930, 3993-4000

Grynberg 35 Com #1, API 30-05-61174

Request Permission to recomplete well as follows:

Status:

Drilled 14 ¾" hole to 887'. Set 887' of 10 ¾" 32.75# casing.

Drilled 7 7/8" hole to 4107'. Set 4107' of 4 1/2" 10.5# casing. Top of cement 167'.

2 3/8" tubing at 3713':

Perforations: 3769'-4000' 54 Holes, 1 SPF

Procedure:

Notify NMOCD and BLM Rep.

Clean off and blade location and road.

Blade with minimal disturbance to allow access and safe working area.

Set and test anchors.

MIRU completion rig.

Bleed pressure off well.

Remove tree and install BOPE. Test to 3000PSI.

Function BOP and hold safety meeting regarding BOP drill and pressure control.

Pull and stand back 3713' of 2 3/8" tbg. Inspect condition of tbg and replace as needed.

Run in bit and casing scraper on tbg.

Circ 2x bottoms up.

TOH. TIH and set CIBP at 3755'.

Contact BLM and NMOCD and test (MIT) casing at 1000 PSI for 20 minutes or as per BLM & NMOCD Rep.

Propose to shoot perfs at:

3742'- 3732, 10'

3717'-3718', 2'

3652'- 3639', 13'. Total = 26 Holes, 1SPF.

Attempt to flow well up 4 1/2" casing.

Run 2 3/8" Tbg to 3630.

Acidize with 2600 gallons 15% HCl, 1000cuft N2/bbl.

Reverse out, swab and attempt to flow well.

```
If no flow:
```

· Pull 2 3/8" tbg

Frac with 30,000 gal KCl water, 10,000 gal liq CO2, 62,000# sand.

RIH with 2 3/8" tbg to 3630'.

Swab and attempt to flow test.

Install production tree and flow test.

Hook up well to sales line.

SECOND TEST PHASE IF THE ABOVE DOES NOT PRODUCE.

If no flow from above procedure:

Notify NMOCD and BLM Rep.

Set CIBP at 3550'

Perf at: 3470-3466', 4

3326-3346, 20

3354-3379, 25

3385-3400, 15'

3405-3407, 2'. Total 66 holes 1SPF

Attempt to flow well up 4 1/2" casing.

Run 2 3/8" Tbg to 3370.

Acidize with 6600 gallons 15% HCl, 1000 cuft N2/bbl.

Reverse out, swab and attempt to flow well.

If no flow:

Pull 2 3/8" tbg

Frac with 66,000 gal KCl water, 22,000 gal liq CO2, 130,000# sand.

Attempt to flow up 4 1/2'.

RIH with 2 3/8" tbg to 3370'.

Swab and attempt to flow test.

Install production tree and flow test.

Hook up well to sales line.

RDMO completion rig.