

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NMLC0289921

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other: UNKNOWN OTH

2. Name of Operator

RAY WESTALL OPERATING, INC

Contact: RENE HOPE

E-Mail: hope_rene5@yahoo.com

8. Well Name and No.
CEDAR LAKE ADI 001

9. API Well No.

30-015-25494

3a. Address

P.O. BOX 4
LOCO HILLS, NM 88255

3b. Phone No. (include area code)

Ph: 575-677-2370

Fx: 575-677-2370

10. Field and Pool, or Exploratory
SWD; CISCO-CANYON

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 26 T17S R30E 2140FNL 660FWL

11. County or Parish, and State

EDDY COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input checked="" type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

SEE ATTACHED PROCEDURE

NM OIL CONSERVATION
ARTESIA DISTRICT

APR 06 2016

Accepted for record

NMOCDF

4/7/16

RECEIVED

Accepted for Record

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #334915 verified by the BLM Well Information System
For RAY WESTALL OPERATING, INC, sent to the Carlsbad

Name (Printed/Typed) RENE HOPE


Title BOOKKEEPER

Signature (Electronic Submission)

Date 03/29/2016

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By



Title

T. PET

Date 3/30/16

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

CFO

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

CEDAR LAKE ADI # 1

02/29/16 – R.U. W.S.U. INSTALL B.O.P.

03/01/16 – R.U. REVERSE UNIT. G.I.H. WITH SHOE, WASH PIPE, DRILL COLLARS AND TBG. TAG @ 6140'. WASH TO 6145'.

03/02/16 – CONTINUE DRILLING TO 6165'.

03/03/16 – CONTINUE DRILLING. MADE 2', QUIT CUTTING. C.O.O.H. HAD APPROXIMATELY 24' CUT TBG IN WASH PIPE. G.I.H. WITH NEW SHOE DRILL TO 6177'.

03/04/16 – CONTINUE DRILLING TO 6201'.

03/07/16 – CONTINUE DRILLING TO 6206', QUIT CUTTING. C.O.O.H., HAD 30' TBG IN WASH PIPE. G.I.H. WITH NEW SHOE.

03/08/16 – START DRILLING - DRILL TO 6235'.

03/09/16 - CONTINUE DRILLING TO 6237', QUIT CUTTING. C.O.O.H., G.I.H. WITH NEW SHOE. TAG @ 5871'.

03/10/16 – ROTATE DOWN TO 6237'. DRILL TO 6264', QUIT CUTTING. C.O.O.H., HAD 44' FISH IN WASH PIPE.

03/11/16 – G.I.H. WITH NEW SHOE. TAG @ 5880', CUT TO 5888'.

03/14/16 – TAG AT 5880'. CUT TO 5883', QUIT CUTTING. C.O.O.H., G.I.H. WITH NEW SHOE, TAG @ 6264'. DRILL TO 6280'.

03/15/16 – CONTINUE DRILLING TO 6308', QUIT CUTTING. C.O.O.H., HAD 14' FISH IN WASH PIPE. G.I.H. WITH NEW SHOE, TAG @ 6308'. CUT TO 6328'. C.O.O.H.

03/16/16 – HAD 15' FISH IN WASH PIPE. G.I.H. WITH NEW SHOE, TAG @ 5870', COULD NOT CUT THROUGH. C.O.O.H.

03/17/16 – G.I.H WITH IMPRESSION BLOCK. TAG @ 5870'. GOT STUCK. WORKED FREE. C.O.O.H., G.I.H. WITH 4 1/2" SWEDGE. WORKED SWEDGE THROUGH TIGHT SPOT. DID NOT FREE UP. C.O.O.H.

3/18/16 – G.I.H. WITH 4 11/16" TAPER MILL. MILLED TO 5870'. C.O.O.H., G.I.H. WITH NEW SHOE. TAG @ 5890'. COULD NOT MAKE ANY HOLE.

3/21/16 – G.I.H. WITH 4 11/16" TAPER MILL. TAG @ 5867'. MILLED TO 5882'. QUIT CUTTING. C.O.O.H.

3/22/16 – G.I.H. WITH NEW 4 5/8" TAPER MILL. TAG @ 5882'. COULD NOT MAKE ANY HOLE. C.O.O.H.

3/23/16 – G.I.H. WITH NEW 4 5/8" MILL. COULD NOT MAKE ANY HOLE. SHUT DOWN.

3/24/16 – GO TO B.L.M. TALKED TO MR. PAUL SWARTZ ABOUT PLUGGING WELL.