NM OIL CONSERVATION

ARTESIA DISTRICT

Action

Form C-141 Revised August 8, 2011

Energy Minerals and Natural Resources

	District II 811 S. First St., Artesia, NM 88210	Energy Minerals and Natural Resource		
	District III	Oil Conservation Division		
	1000 Rio Brazos Road, Aztec, NM 87410 District IV	1220 South St. Francis Dr.		
	1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505		
	Re	elease Notification and Corrective		
	NABIL/1395/1/13	OPERATOR		
	Name of Company: COG Oper	ating LLC 224/37 Contact:		

District I 1625 N. French Dr., Hobbs, NM 88240

NABILO1.3	951443		OPERATOR	🛛 Initial Report	Final Report
Name of Compan	y: COG Operating I	LC 224/3	Contact:	Robert McNeill	
Address: 60	0 West Illinois Ave, Midland		Telephone No.	432-683-7443	
Facility Name:	HONEY GRAHAM STATE	COM #002H	Facility Type:	Tank Battery	
Surface Owner:	State	Mineral Owner	•	API No. 30-015	-41234

Surface Owner: State Mineral Owner:

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
c	29	26S	28Ē	130	North	1980	West	Eddy

Latitude 32.02008 Longitude 104.11170

NATURE OF RELEASE

Type of Release:	Volume of Release: 5bbls of oil Volume Recovered: 4.5bbls of oil				
Oil and Produced Water	19bbls of produced water 18bbls of produced water				
Source of Release:	Date and Hour of Occurrence: Date and Hour of Discovery:				
FWKO Tank	05-05-2016 08:00am 05-05-2016 08:00am				
Was Immediate Notice Given?	If YES, To Whom?				
🔲 Yes 🛛 No 🖾 Not Required					
By Whom?	Date and Hour:				
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.				
🔲 Yes 🖾 No					
If a Watercourse was Impacted, Describe Fully.*					
······································					
Describe Cause of Problem and Remedial Action Taken.*					
	*				
The dump valve on the FWKO failed. Replaced the faulty dump valve wit	h a new valve.				
Describe Association of Classical Association Televist					
Describe Area Affected and Cleanup Action Taken.*					
This release was caused when a dump valve failed on a FWKO. The spill	was contained incide the lined facility. All free fluid has been recovered				
This recease was caused when a dump varve failed on a r witter. The spin	was combined inside the linea factory. All free hand has been recovered				
I hereby certify that the information given above is true and complete to the	te best of my knowledge and understand that pursuant to NMOCD rules and				
	otifications and perform corrective actions for releases which may endanger				
	NMOCD marked as "Final Report" does not relieve the operator of liability				
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health					
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other					
federal, state, or local laws and/or regulations.					
Simplement 7	OIL CONSERVATION DIVISION				
Signature: Racent Aurop.	Signed By Milly Dramula				
Printed Name: Robert Grubbs Jr.					
	Approved by Environmental Specialist:				
Title: Senior Environmental Coordinator	Approval Date: 5 8 0 Expiration Date: N/A				
E-mail Address: rgrubbs@concho.com	Conditions of Approval:				
	Remediation per O.C.D. Rules & Guidelinds				
Date: 05-16-2016 Phone: 432-683-7443	SUBMIT REMEDIATION PHOPOSAL NO				
Attach Additional Sheets If Necessary	LATER THAN: 1/1/11/ 2RP- 3/97				

State of New Mexico

MAY 16 2016

Supple Eropic appropriate District Office in Recentiance with 19.15.29 NMAC.