

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1161100296609

Name of Company: BOPCO, L.P. <i>2100737</i>		OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Contact: Bradley Blevins
Facility Name: PLU 183Q		Telephone No. 575-887-7329
		Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner:	API No. 30-015-33224

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	7	24S	30E	330		1980		Eddy

Latitude: 32.240755 Longitude: 103.919828

NATURE OF RELEASE

Type of Release: Crude oil and Produced Water	Volume of Release: 4 barrels oil and 12 barrels PW	Volume Recovered 1 barrel oil and 2 barrels PW
Source of Release: Flowline	Date and Hour of Occurrence: 6-2-16 8:30am	Date and Hour of Discovery 6-2-16 9:06 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	NM OIL CONSERVATION
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. ARTESIA DISTRICT	

JUN 06 2016

RECEIVED

Describe Cause of Problem and Remedial Action Taken.

A hole developed in the flowline due to corrosion, a vacuum truck was called to the location to recover the standing fluid.

Describe Area Affected and Cleanup Action Taken.*

Flowline developed a hole along edge of lease road; the fluid ran into the pasture area. A vacuum truck was called to the location to recover the standing fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>		OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman		Approval Date: <i>6/8/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: bblevins@basspet.com		Conditions of Approval:	
Date: <i>6-6-16</i> Phone: 432-214-3704		Remediation per O.C.D. Rules & Guidelines	
		SUBMIT REMEDIATION PROPOSAL NO	
		LATER THAN: <i>7/14/16</i>	

* Attach Additional Sheets If Necessary

2RD-3716