	NW	All CONORDULE		
Form 3160-5 (August 2007) DEPARTMENT OF T	HE INTERIOR	. OIL CONSERVATIO 811 S. FIRST STRE ARTESIA, VII 882	et o	DRM APPROVED MB No. 1004-0137 pires: July 31, 2010
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELI				
Do not use this form for propose abandoned well. Use Form 3160-3	als to drill or to re-enter	ал 🛛	dian, Allottee o	Tribe Name
SUBMIT IN TRIPLICATE - C	Other instructions on page 2.	7. If Ui	nit of CA/Agree	ment, Name and/or No.
1. Type of Well Gas Well Other			Name and No. Federal #1	
2. Name of Operator Nadel and Gussman Permian, LLC			9. APT Well No. 30-005-61875	
3a. Addross 601 N. Marlendeld, Suite 508 Mildland, TX 79701	3b. Phone No. (include area code) 432-682-4429		10. Field and Pool or Exploratory Area Sams Ranch (Grayburg)	
4. Location of Well (Footage, Sec., T., R., M., or Survey Descrip SWNW Sec 12-T14S-R2BE NMPM		11. Country or Parish, State New Mexico		
12. CHECK THE APPROPRIAT	E BOX(ES) TO INDICATE NAT		<u>.</u>	ER DATA
TYPE OF SUBMISSION		TYPE OF ACTION		
Notice of Intent	Deepen	Production (S	tart/Resume)	Water Shut-Off
Subsequent Report	New Construction	Recomplete		Other
Final Abandonment Notice	tion Plug and Abandon	<ul> <li>Temporarily</li> <li>Water Dispos</li> </ul>		
Nadel and Gussman Permian, LLC is submitting this sund inspection. The reason for abandonment was uneconomic				is finished, and ready fo <del>r</del>
	-	d for record 10CD	NI	MOIL CONSERVATION ARTESIA DISTRICT JUN 09 2016 RECEIVED
<ol> <li>I hereby certify that the foregoing is true and correct. Name (Printed/Typed)</li> </ol>	·····			<u> </u>
Joel Martin	Title Engin	eering Manager		
Signature Dant	Date 04/21	/2014		
THIS SPA		···-	ISE	
	CE FOR FEDERAL OR			
Approved by	Assie	state office L Rant Field Mar s And Minerals	S	JUN <b>02</b> 2016
Approved by S Ruben J. Sanchez. Conditions of approval, if any, are attached. Approval proves of this notice that the applicant holds legal or equitable title to those rights in the s entitle the applicant to conduct operations thereon.	Assis Land Title	s And Mineral	S	ate

~

(Instructions on page 2)

## NADEL AND GUSSMAN PERMIAN

÷

