

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

JUL 06 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1619028356

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production	Contact	Jake Harrington, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	432-214-5175
Facility Name	Ross Ranch 10 Fed 1 SWD	Facility Type	SWD

Surface Owner	Federal	Mineral Owner	Federal	API No.	30-015-29605
---------------	---------	---------------	---------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	10	26S	31E	1980'	North	660"	East	Eddy

Latitude: 32.059235486

Longitude: -103.75905787

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	10bbls	Volume Recovered	10bbls
Source of Release	4"x3" reducer	Date and Hour of Occurrence	July 1, 2016 @ 1:14 PM	Date and Hour of Discovery	July 1, 2016 @ 1:14 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Shelly Tucker, BLM Mike Bratcher, OCD		
By Whom?	Jake Harrington, Production Foreman	Date and Hour	Shelly Tucker, BLM July 1, 2016 @ 5:00 PM Mike Bratcher, OCD July 1, 2016 @ 5:05 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
A 4"x3" reducer on the basic sediment and water line had a pin hole. A vacuum truck was contacted and pulled the tank empty to stop the release. Repairs have been made and the facility is back in service.

Describe Area Affected and Cleanup Action Taken.*
The release was approximately 10bbls produced water into lined containment and all 10bbls were recovered by vacuum truck. The liner was checked for holes and no holes were found. No further action is necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher	OIL CONSERVATION DIVISION		
Printed Name: Sheila Fisher	Signed By: Mike Bratcher		
Title: Field Admin Support	Approved by Environmental Specialist:		Approval Date: 7/8/16
E-mail Address: Sheila.Fisher@dvn.com	Conditions of Approval: FINAL		Expiration Date: N/A
Date: 7/6/16	Phone: 575.748.1829		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-3767