Office Submit I Copy To Appropriate District		State of New Me			Form C	
District I - (575) 393-6161	Energy,	Minerals and Natu	ral Resources	WELL API NO.	Revised July 18	3, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283	OII C	ONSEDVATION	DIVISION	30-015-01659		
811 S. First St., Artesia, NM 88210 <u>District III</u> (505) 334-6178	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.			5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	12	Santa Fe, NM 87		STATE 6. State Oil & G	FEE L	
<u>District IV</u> - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM		Suita i O, i vivi O ,	, 303	647	as Lease No.	1
87505	PICES AND DE	DODTS ON WELLS			an I In it A annument Ni	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name		
				Empire Abo Unit (309164)		
1. Type of Well: Oil Well	Gas Well 🔲	Other		8. Well Number	026A	
2. Name of Operator				9. OGRID Num	ber	
Apache Corporation 3. Address of Operator				873 10. Pool name o	- Wildoot	
303 Veterans Airpark Lane, Suite	1000 Midland,	TX 79705		Empire; Abo (220		
4. Well Location						
Unit Letter N	: 660 fee	t from the South	line and 1980	feet fro	om the West	line
Section 32			inge 28E	NMPM	County Eddy	
The control of the co	11. Elevation	n (Show whether DR,	RKB, RT, GR, etc.)			
Star Walters		3663' GL				-34.45
12 Charle	A nonconsista i	Day to Indicate N	ntuma of Nintina I)	. D-4-	
12. CHECK	Appropriate	Box to Indicate N	ature or motice, i	Report of Other	Data	
NOTICE OF I	NTENTION :	TO:	SUBS	SEQUENT RE		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO					ALTERING CASING	
TEMPORARILY ABANDON	-		COMMENCE DRIL		P AND A	
PULL OR ALTER CASING [-	COMPL [CASING/CEMENT	JOB 🗆		
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM						
OTHER:	J	П	OTHER:			П
13. Describe proposed or com	pleted operation	is. (Clearly state all r		give pertinent dat	es, including estimat	ed date
of starting any proposed w	vork). SEE RUL	LE 19.15.7.14 NMAC	C. For Multiple Com	pletions: Attach	wellbore diagram of	
proposed completion or re	completion.					
Apache would like to perform the foll	owing work:					
Producing Interval: 5,651-6,123						
- · · · · · · · · · · · · · · · · · · ·	f		f = 4dt = - 4 = d = 4 = t =	- 6		186
Objective: TA Wellbore. Currently pe o bring it back to production.	rrorming geologi	icai and petrophysical	i studies to determin	•	•	j wellbore
- '				D	RECEIVE	
Procedure: I. POOH with rods and pump						
2. Set a CIBP @ 5,600' and dump ba	ail 35' of cmt			;	EEB 00	
Circulate fluid and pressure test ca					**	
Record the test on a chart and sub	imit to OCD for			ارد ****	M OIL CONSER ARTESIA DISTR	IN.
		TA status may be	-		RASINGO IIO .	
	successful MIT test is performe Contact the OCD to schedule th			•		
Spud Date: 01/26/1960						
		so it may be witi	nessed.		SST PRED	2/1/
II	[001 1100	'تك
I hereby certify that the information	i above is true at	na complete to the be	est of my knowledge	and belier.		
(),	11					
SIGNATURE Sabel trusson		TITLE Regulatory Analyst		DATE 01/09/2017		
m Isabal Hudaaa			leahal hudean@	chacors com	10) m (433) 040 44	40
Type or print name Isabel Hudson	**************************************	E-mail address	: isabel.hudson@apa	checorp.com pp	HONE: (432) 818-11	42
For State Use Only	/	_				
APPROVED BY: Peutage	NAN	TITLE CO	mplimes	OPacolo	TE 2/9/1.	7
Conditions of Approval (if any):						



January 6, 2017

Empire ABO Unit # H-26 Legal Name: Empire ABO Unit #026A API # 30-015-01659

Eddy County, NM

Producing Interval: 5,651-6,123'

<u>Objective</u>: TA Wellbore. Currently performing geological and petrophysical studies to determine feasibility for recompletion. Evaluating wellbore to bring it back to production.

Procedure:

- 1. POOH with rods and pump
- 2. Set a CIBP @ 5,600' and dump bail 35' of cmt
- 3. Circulate fluid and pressure test casing to 500 psi
- 4. Record the test on a chart and submit to OCD for approval

