Form 3160-5 (April 2004)

OCD-ARTESIA UNITED STATES

DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

5. Lease Senal No.

NMLC029426B

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

abandoned we	ell. Use Form 3160-3 (A	(PD) for such pro	posals.		
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No.	
1. Type of Well Gas Well Other					
2. Name of Operator Marbob Ener	rgy Corporation			Oxy Pote	eet Strawberry Federal #1
3a. Address PO Box 227, Artesia, NM 88211-0227		3b. Phone No. (include area code) 505-748-3303		30-015-31322 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Description)			ł	v; Wolfcamp, SE
1650 FNL 660 FEL, Sec. 10-T	17S-R31E, Unit H			11. County or Eddy Co	r Parish, State
12. CHECK AI	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, R	EPORT, OR	OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent Subsequent Report	Acidize Alter Casing Casing Repair Change Plans	Deepen Fracture Treat New Construction Plug and Abandon	Production (Sta Reclamation Recomplete Temporarily Ab	, 	Water Shut-Off Well Integrity Other
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
Attach the Bond under which the following completion of the inv	ctionally or recomplete horizontally ne work will be performed or provice volved operations. If the operation real hal Abandonment Notices shall be f	y, give subsurface location de the Bond No. on file we results in a multiple complete.	ns and measured and tru with BLM/BIA. Required letion or recompletion in	e vertical depths ed subsequent rep n a new interval,	of all pertinent markers and zones. ports shall be filed within 30 days a Form 3160-4 shall be filed once

Marbob Energy Corporation proposes to plug & abandon this well as follows:

Notify BLM 24 hours before starting plugging.

- 1. POOH w/ pkr. Set 5 1/2" CIBP @ 8500' (perfs @ 8597'-9634'). Cap w/ 35' cmt.
 2. Spot 100' plug @ 5170'. PERF & SQUEEE. TAGE
 3. Perf sqz 100' plug @ 4550' (9 5/8" shoe @ 4500'). WOC. Tag.

- 4. Sqz casing leak @ 3629'-3661'.
- 5. Perf sqz 100' plug @ 750' (13 3/8" shoe @ 625', salt @ 720'). WOC. Tag.
- 6. Perf @ 60'. Circ cmt to surface.

RECEIVED 7. Cut off wellhead & install dry hole marker.

> MAR 3 1 2006 OOD-AFTERIA

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. Thereby certify that the foregoing is true and correct Name (Printed/Typed)						
Diana J. Briggs	Title Production Analyst	Ø				
Signature Maria Maria	Date N	03/24/2000				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by	Title	Date				
Conditions of approval, if any, are attached. Approval of this notice does not warrancertify that the applicant holds legal or equitable title to those rights in the subject lewhich would entitle the applicant to conduct operations thereon.						

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction.