

WELL SERVICE REPORT

OWNER: PAUL & PAUL LEASE LOWE B WELL: 1 DATE: 3-14-84

FIELD: _____ COUNTY: _____ STATE: _____ T.D.: _____

FLUID LEVEL: _____ PERF. OR O.H.: _____ CASING: _____

REASON FOR WORK: HOLE IN TUBING

PULLED		DESCRIPTION OF ITEM	FEET	JOINTS
RUN				
		PULLED ROD AND PUMP OUT OF WELL		
		DRUPPED STANDING VALVE AND		
		PREPARED UP IN TUBING.		
		RAN OUT OF WELL WITH TUBING AND		
		FOUND HOLE IN 65 JOINTS.		
		REPAIRED 1-84 JOINT OF TUBING		
		AND RE-RAN TUBING AND (LIFT)		
		TUBING AND RIG IN GOOD SHAPE		
		88 JOINTS OF TUBING		
		108 - 3/4 ROD		
		1 - 3/4 X 8 FT SUG		
		1 - 3/4 X 6 FT SUG		
		1 - 3/4 X 2 FT SUG		
		PUMP - NO. LH 119 10 FT. METAL		
		TRAIL BARREL, DOUBLE VALVE		
		BOOSTER HOLD DOWN.		
		65 1/2 IN. STROKE - 5/8 IN. P.D.		

REMARKS AND DETAILS OF WORK:

SIGNED: _____

CHECK IF ADDITIONAL REMARKS ON BACK ☐