

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NMM 064489
6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE – Other instructions on page 2.

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Slayton Resources Inc.

3a. Address

P.O. Box 2035 Roswell, NM 88202

3b. Phone No. (include area code)

575-623-7184

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec. 7, T14S, R28E 1060 FSL 2180 FWL Unit N

7. If Unit of CA/Agreement, Name and/or No.

N

8. Well Name and No.

Cannonball Fed #1

9. API Well No.

30-005-62658

10. Field and Pool or Exploratory Area

Wildcat (Strawn)

11. Country or Parish, State

Chaves NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>Work Over</u>
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Moved in Service Unit
Pulled 2 7/8" tubing and packing
Reran new packer and 2 3/8" tubing
Moved in swab crew
Lost part of the swab assembly in tubing
awaiting service rig to pull tubing

7-10-17
Accepted for record - NMOCD

ACCEPTED FOR 3 MONTH PERIOD
ENDING SEP 29 2017

NM OIL CONSERVATION
ARTESIA DISTRICT
JUL 10 2017

14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)

Paul Slayton

Title Consultant

RECEIVED

Signature

Paul Slayton

Date June 6, 2017

THIS SPACE FOR FEDERAL OR STATE OFFICE USE
ACCEPTED FOR RECORD

Approved by

(DAVID H. GLASS) DAVID H. GLASS

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

DAVID H. GLASS

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person known to make any fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Accepted For Record Only! Approval Subject To Putting Well On Continuous Production And Keeping Well On Continuous Production Or Plugging Well With An Approved Plugging Program!

false,